

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

Form C-141
Revised October 10, 2003

DEC 10 2010
HOBBSCOCD
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report

☐ Final Report

Name of Company	Southern Union Gas Services	Contact	Rose Slade
Address	P.O. Box 1226 Jal, New Mexico 88252	Telephone No.	432-940-5147
Facility Name	Trunk "O" 12610	Facility Type	Natural Gas Pipeline
Surface Owner	State of New Mexico	Mineral Owner	API No 30-025- 28822

LOCATION OF RELEASE

38822 15

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	23	23S	36E					Lea

Latitude 32 degrees 17.414' Longitude 103 degrees 14.628'

WTR 150'

NATURE OF RELEASE

Type of Release	Natural Gas, Crude Oil and Produced Water	Volume of Release	9 BBLS	Volume Recovered	5 BBLS
Source of Release	30-Inch Steel Pipeline (Low Pressure)	Date and Hour of Occurrence	December 6, 2010	Date and Hour of Discovery	December 6, 2010 - 1030 hours
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Failure of a segment of the thirty (30) low pressure steel pipeline resulted in the release of approximately nine (9) barrels of a mixture of crude oil and produced water. An unknown volume of natural gas was released to the atmosphere. A vacuum truck was able to recover approximately five (5) barrels of the released mixture. Following discovery of the release, the pipeline was taken out of service and depressurized. Following the repair of the pipeline, the line was placed back in service.

Describe Area Affected and Cleanup Action Taken.*

An area of range land measuring approximately 12,500 square feet was affected by the release. The release will be remediated to NMOCD regulatory guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rose L. Slade</i>	OIL CONSERVATION DIVISION		
Printed Name: Rose L. Slade	Approved by District SUPERVISOR ENVIRONMENTAL ENGINEER		
Title: E.H.S. Compliance Specialist	Approval Date: 12.10.10	Expiration Date: 3.10.10	
E-mail Address: rose.slade@sug.com	Conditions of Approval:		
Date: 12-10-2010 Phone: 432-940-5147	SUBMIT FINAL C-141 w/ Docs BY 12.10.2010		

* Attach Additional Sheets If Necessary

n LWS 1034740711
p LWS 1034741173