

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
DEC 28 2010
NMOCD ARTESIA

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

7KMW 1101950199

OPERATOR Initial Report Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	McIntyre DK Federal (Northwest Central)	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	Lease No. NMNM-86025



LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	17	17S	30E					Eddy

Latitude 32 49.804 Longitude 103 59.782

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	23bbls	Volume Recovered	20bbls
Source of Release	Oil Tank	Date and Hour of Occurrence	12/15/2010	Date and Hour of Discovery	12/15/2010 8:00a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
The equalizer line was plugged causing the oil tank to overflow. The plugged equalizer line has been cleaned out.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 23bbls of oil was released from the oil tank and we were able to recover 20bbls with a vacuum truck. The oil traveled south on the pad location 3' x 100', and then off the pad roughly 30' towards a prior spill location. All oil has been picked up with a vacuum truck, pad material has been scraped of contaminates, tanks and lines have been steamed. (Well location on the same pad, McIntyre Federal #6, (API#) 30-015-20972).					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Approved by District Supervisor:	
Title:	HSE Coordinator	Approval Date:	2/23/2011
E-mail Address:	jrusso@conchoresources.com	Expiration Date:	
Date:	12/17/2010	Phone:	432-212-2399
		Conditions of Approval:	Attached <input type="checkbox"/>

Remediation per OCD Rules & Guidelines. **SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:**
3/23/2011

2RP-573

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@conchoresources.com]
Sent: Tuesday, December 28, 2010 8:04 AM
To: Bratcher, Mike, EMNRD; terry_gregston@nm.blm.gov
Cc: Pat Ellis; james_amos@nm.blm.gov; Ike.Tavarez@tetrattech.com; Dorey, Kim; tom.k.franklin@tetrattech.com
Subject: C-141 Initial Report - Mcintyre DK Federal - Northwest Central
Attachments: MCINTYRE DK FEDERAL (NORTHWEST CENTRAL TANK BATTERY) -- DATE OF RELEASE -- 12-15-2010.PDF

Please see attached the C-141 Initial Report for a release that occurred on 12/15/2010.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.