




GW - 028 MONITORING REPORT Annual GW Monitoring Rep MAPS (Feb 2011)



- LEGEND:
- ◆ MONITORING WELL
 - RECOVERY WELL
 - IRRIGATION WELL
 - ABANDONED WELL
 - SHALLOW AQUIFER POTENTIOMETRIC SURFACE CONTOURS



NAVAJO REFINING COMPANY
ARTESIA REFINERY, EDDY COUNTY, NEW MEXICO
FIRST SEMIANNUAL EVENT 2010 (MAR-APR)

**SHALLOW AQUIFER
POTENTIOMETRIC SURFACE MAP**

FIGURE
3