GW - 028

MONITORING REPORT

Annual GW Monitoring Rep

MAPS

(Feb 2011)

LEGEND:

- BENZENE GROUNDWATER EXCEEDANCE AREA
- MONITORING WELL
- RECOVERY WELL
- IRRIGATION WELL
- ABANDONED WELL

0 800 1,600 2,400 3,200 Feet

GRAPHIC SCALE

New Mexico

NAVAJO REFINING COMPANY
ARTESIA REFINERY, EDDY COUNTY, NEW MEXICO

2010 ANNUAL GROUNDWATER REPORT

BENZENE CRITICAL GROUNDWATER SCREENING LEVEL EXCEEDANCE AREAS FIRST SEMI-ANNUAL EVENT 2010

ARCADIS

FIGURE 13