

RECEIVED

State of New Mexico

Form C-141
Revised October 16, 2004

APR 18 2010

Conservation Div

Subpart 2 Code of Appr
District Office in acc
with Rule 116
side of form

HOBBSOCD

1700 South St. Francis

Santa Fe, NM 87505

Release Notification and Corrective Action

OPERATOR

Initial Report

Final Report

Name of Company Penroc Oil Corporation	Contact Royce Eades
Address PO Box 2769, Hobbs, New Mexico 88241	Telephone No. 575-492-1236
Facility Name Penroc State GC Lease	Facility Type Spill in diked area of battery.

Surface Owner State of New Mexico	Mineral Owner State of New Mexico	Lease No. L-6377
-----------------------------------	-----------------------------------	------------------

LOCATION OF RELEASE

STATE GC #002

APR 30 025 38617 00:00

Unit Letter O	Section 7	Township 22S	Range 35E	Feet from the 660	North/South Line South	Feet from the 1980	East/West Line East	County Lea
------------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude

Longitude

NATURE OF RELEASE

Type of Release Produced water/oil	Volume of Release minimal	Volume Recovered 0
Source of Release Oil Hauling truck, flow line	Date and Hour of Occurrence Unknown	Date and Hour of Discovery Unknown
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? No <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

WATER @ 40'

Describe Cause of Problem and Remedial Action Taken.*

Possible leak in line inside diked area. Oil Hauling trucks not emptying hose prior to disconnect. These releases occurred prior to Penroc Oil Corporation having title to lease, however it recognized it now the responsibility of Penroc Oil Corporation to rectify problems.

Describe Area Affected and Cleanup Action Taken.*

Stain in diked area, stain at end of load line. Penroc will pick up oil stained dirt, test to clean. The contaminated soil will be taken to approved disposal. Then the oil stained dirt will be replaced with clean dirt.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Royce Eades	Approved by ENV ENGINEER: District Supervisor:	
Title: Operations Manager	Approval Date: 06/09/10	Expiration Date: 08/09/10
E-mail Address: royceeades@penrocoil.com	Conditions of Approval: SUBMIT FINAL C-141 BY 08/09/10 NOTE: DELINEATE OUTSIDE OF DIKED AREA AT LEAST END & SOUTH	Attached <input type="checkbox"/>
Date: 4/19/2010 Phone: 575-492-1236	IRP-10-6-2555	

SIDE OF DIKED AREA, ALSO AT LOAD LINE. DELINEATE INSIDE AND OUTSIDE DIKED AREA BOTH HORIZONTALLY AND VERTICALLY.

* Attach Additional Sheets If Necessary