

RECEIVED APR 29 2010

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-05123

Release Notification and Corrective Action

AKMW 1107650803

OPERATOR

Initial Report

Final Report

Name of Company	SandRidge Energy	270265	Contact	Ron Ragland
Address	3504 NW County Road Hobbs, N.M.		Telephone No.	(575) 392-9797
Facility Name	State A&B Battery		Facility Type	Battery

Surface Owner	State	Mineral Owner	Lease No.	B-2613 & B-3014
---------------	-------	---------------	-----------	-----------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	16	17S	31E	1650'	South	660'	East	Eddy

Latitude 32.83182 Longitude -103.86765

NATURE OF RELEASE

Type of Release	Oil & Water	Volume of Release	50 bbls.	Volume Recovered	35 bbls.
Source of Release	Flowline	Date and Hour of Occurrence	4/28/2010 6:00 a.m.	Date and Hour of Discovery	4/28/2010 9:30 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Randy NMOCD - Artesia Office			
By Whom?	Roy Munoz	Date and Hour	4/28/2010 2:45 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

3" X 2' flowline had a hole in nipple Replaced nipple and called vac. truck

Describe Area Affected and Cleanup Action Taken.\*

Inside dike - (20' x 24') & continued 2400' down a ravine. (The 1<sup>st</sup> 1000' was 6" wide. The rest was 1400' X 2' wide).  
Affected area was all dirt.  
Cleaned area with vac. truck recovering 11 bbls. from dike and 24 bbls. from ravine.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:	Ron Ragland	<i>By Mary Jo Turner</i>
Printed Name:	Ron Ragland	
Title:	Sr. Prod. Foreman	
E-mail Address:	rragland@sdrge.com	
Date:	April 29, 2010	Phone: (575) 392-9797

Approved by District Supervisor:	<i>Mike Benavides</i>
Approval Date:	3/17/11
Expiration Date:	
Conditions of Approval:	Attached <input type="checkbox"/>
Remediation per OCD Rules & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:</b>	
<u>4/12/11</u>	

\* Attach Additional Sheets If Necessary

2RP-648

**Bratcher, Mike, EMNRD**

---

**From:** Mary Jo Tuner [mturner@sdrge.com]  
**Sent:** Thursday, April 29, 2010 3:18 PM  
**To:** Bratcher, Mike, EMNRD  
**Attachments:** 20100429171743611.tif

This E-mail was sent from "RNPF8999C" (Aficio MP C2050).

Scan Date: 04.29.2010 17:17:43 (-0400)