

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*nkmw 1108951419*

**OPERATOR**  Initial Report  Final Report

Name of Company	COG OPERATING LLC <i>229137</i>	Contact	Kanicia Carrillo
Address	550 W. Texas, Suite 100 Midland, TX 79701	Telephone No.	432-685-4332
Facility Name	8" Loco Hills SWD line	Facility Type	SWD waterline (.4 miles South of the Jackson B #5)
Surface Owner	State	Mineral Owner	
		Lease No.	30-015-04037

**\*\* Jackson B #5, Operator - Burnett Oil Company LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	1	17S	30E	660	North	1980	East	Eddy

Latitude N 32° 48.409 Longitude W 103° 55.067

**NATURE OF RELEASE**

Type of Release	Produced Water	Volume of Release	300bbls	Volume Recovered	260bbls
Source of Release	SWD valve	Date and Hour of Occurrence	09/02/09	Date and Hour of Discovery	09/02/09
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - OCD		
By Whom?	Pat Ellis	Date and Hour	08/10/09 4:25pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
8" line open due to faulty installation. We picked up water and removed 12" of the contaminated soil.					
Describe Area Affected and Cleanup Action Taken.*					
Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for your approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

**OIL CONSERVATION DIVISION**

Signature:	<i>KC</i>	Approved by District Supervisor	<i>Mike Bratcher</i>
Printed Name:	Kanicia Castillo	Approval Date:	<i>3/30/11</i>
Title:	Regulatory Analyst	Expiration Date:	
E-mail Address:	kcarrillo@conchoresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	09/14/09	Phone:	432-685-4332

\* Attach Additional Sheets If Necessary

REMEDATION per OCD Rules and  
Guidelines. SUBMIT REMEDIATION  
PROPOSAL BY: *4/30/11* *2RP-675*

**Bratcher, Mike, EMNRD**

---

**From:** Kanicia Castillo [KCarrillo@conchoresources.com]  
**Sent:** Monday, September 14, 2009 3:30 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Pat Ellis  
**Subject:** C141 Loco Hills SWD line  
**Attachments:** Loco Hills SWD line C141.pdf

Mike,

Let me know if you need additional info.

Thank you,

*Kanicia Castillo*

Regulatory Analyst



COG Operating LLC

550 West Texas Ave, Suite 1300

Midland, TX 79701

432-685-4332

"A smile is a curve that sets everything straight!"

---

This inbound email has been scanned by the MessageLabs Email Security System.

---

## Bratcher, Mike, EMNRD

---

**From:** Pat Ellis [PELLIS@conchoresources.com]  
**Sent:** Tuesday, September 08, 2009 8:21 AM  
**To:** Bratcher, Mike, EMNRD  
**Subject:** Leak on 8" SWD line at Loco Hills SWD

Mike, I wanted to notify you of a leak that we had last Wednesday on our 8" Loco Hills SWD line. I thought you had been notified but found out this morning we had dropped the ball. We had a valve on the 8" line open due to faulty installation and released approximately 300 bbls of produced water. We picked up 260 bbls of water. The spill path was 6' x 900' and ran down a Conoco /Phillips ROW. A one call was made Friday and we removed 12" of the contaminated soil. I have Tetra Tech set up to sample the spill area. We will submit a C-141 this week.

The nearest well is Burnett Oil Company (Jackson B # 5) 460' FEL, 100' FNL, Sec. 25, T17S, R30E, Eddy CO. The release site is .4 miles south of this location. GPS coordinates are N 32 deg 48.409 and W 103 deg 55.067. If there are further questions please give me a call. Thanks, Pat.



Patrick Ellis  
EH&S Advisor  
Office 432.686.3023  
Cell 432.230.0077  
Fax 432.687.8008  
[pellis@conchoresources.com](mailto:pellis@conchoresources.com)

---

This inbound email has been scanned by the MessageLabs Email Security System.

---