

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

FEB - 2 2009

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-02815

Release Notification and Corrective Action

N KMLW 1109438979

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Tandem Energy Corporation	236/83	Contact	Dean Mathiews
Address	120 S. Main Street, Suite 350, Victoria, TX 77901		Telephone No.	1-361-550-2800
Facility Name	Nunlee Federal #006		Facility Type	Pumping Unit

Surface Owner	Mineral Owner	Lease No. NM14843
---------------	---------------	-------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
1	35	16S	29E	1650	South	300	East	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release	Saltwater	Volume of Release	30 bbls	Volume Recovered	15 bbls
Source of Release	Stuffer box	Date and Hour of Occurrence	01/13/2009 a.m.	Date and Hour of Discovery	01/13/2009 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher at OCD, Jim Amos, BLM		
By Whom?	Brandi Barthels	Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

Stuffer box leaked. The remedial action plan will be developed and executed for the site after soil sampling is conducted.

Describe Area Affected and Cleanup Action Taken.\*

Area of spill is 180'x100'. The remediation plan will be developed and executed based upon the soil analysis results.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Dean Mathiew</u>	OIL CONSERVATION DIVISION	
Printed Name: Dean Mathiews	Approved by District <u>Mike Bratcher</u>	
Title: Operations Manager	Approval Date: <u>4/4/11</u>	Expiration Date:
E-mail Address: dmathiews@platenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 01/27/2009 Phone: 361-550-2800	REMEDATION per OCD Rules and Guidelines. SUBMIT REMEDIATION PROPOSAL BY: <u>5/4/11</u>	

\* Attach Additional Sheets If Necessary

2RP-693