District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr. Santa Fe. NM 87505

State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

RECEIVED Form C-141

Revised October 10, 2003

MAY 19 2011

Submit 2 Copies to appropriate
District Office in accordance

NMOCD ARTESIAith Rule 116 on back
side of form

1220 S. St. Francis Dr., Santa Fe	ınta F	e, NM 875	505 L	141410			□	side of form			
Release Notification and Corrective Action											
MLB 1114046571 OPE					ATOR						
Name of Company					Contact						
Yates Petroleum Corporation Address					Robert Asher Telephone No.						
105 South 4th Street, Artesia, NM 88210					575-748-1471						
Facility Name					Facility Type Battery						
Serrano Federal #1			30-015-28166	30-015-28166 I							
Surface Owner			Mineral C Federal)wner				Lease No. NM-92748			
Federal											
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County											
M 11	- 1 0				South	1		West Eddy			
Latitude 32.67000 Longitude 104.46139											
NATURE OF RELEASE											
Type of Release Crude Oil/Produced Water Mix					Volume of Release 150 B/O & PW Mix			Volume Recovered 130 B/O & PW Mix			
Source of Release					Date and Hour of Occurrence			Date and Hour of Discovery			
Produced water tank Was Immediate Notice Given?					5/3/2011 AM 5/3/2011 AM If YES, To Whom?						
, as introduced the same of the	equired										
By Whom? Polyert Asher/Votes Petroleum Correction					Date and Hour 5/3/2010; PM (E-mail)						
Robert Asher/Yates Petroleum Corporation Was a Watercourse Reached?					If YES, Volume Impacting the Watercourse.						
Yes 🗵 No N/A If a Watercourse was Impacted, Describe Fully.*											
N/A											
Describe Cause of Problem and Remedial Action Taken.* Water transfer pump air locked, causing produced to overflow from water leg and hatch of tank. Vacuum truck called.											
Describe Area Affected and Cleanup Action Taken.* Area approximately 30' X 75' all contained inside berm, vacuum truck picked up remaining oil and produced water. Impacted soils to be excavated and											
hauled to an NMOCD approved facility. Initial vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for											
documentation). Analytical results will determine if closure can be requested or a work plan will be submitted. Depth to Ground Water: 50-99' (80' per N.M. Office of the State Engineer), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10.											
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger											
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability											
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other											
federal, state, or local laws and/or regulations.											
					OIL CONSERVATION DIVISION						
Signature:					Approved by District Supervisor:						
Printed Name: Robert Asher					Approved by District Supervisor:						
Title: Environmental Regulatory Agent					Approval Date: 5/20/2011 Expiration Date:						
E-mail Address: boba@yatespetroleum.com					Conditions of Approval:						
T. T. 10 0011					Remodiation per OCD Rules &						
Date: Thursday, May 19, 20 Attach Additional Sheets	امنین	idolines SUBMIT REMEDIATION									
PROPOSAL NOT LATER I HAN. $\sim 10^{-10}$											
6/20/2011											

Bratcher, Mike, EMNRD

From:

Bob Asher [BobA@yatespetroleum.com]

Sent:

Wednesday, May 04, 2011 4:16 PM

To:

Bratcher, Mike, EMNRD

Cc:

Jerry Fanning

Subject:

Release (Serrano Federal #1 Battery)

Mike,

Yates Petroleum Corporation is reporting a release that occurred Wednesday, May 4, 2011.

Serrano Federal #1 Battery 30-015-28166 Section 11, T19S-R25E Eddy County, New Mexico

Released: 50 B/PW from transfer pump that locked up, vacuum truck called.

An Initial C-141 will be submitted with complete information.

Thank you.

Robert Asher

Yates Petroleum Corporation

Office: (575) 748-4217

Cell: (575) 365-4021

Fax: (575) 748-4662

boba@yatespetroleum.com