



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON

Governor

Jennifer A. Salisbury

Cabinet Secretary

Lori Wrotenbery

Director

Oil Conservation Division

Field Inspection Program

"Preserving the Integrity of Our Environment"

11-May-01

C E LARUE & B M MUNCY JR

PO BOX 1370

ARTESIA, NM 88211-1370

BEFORE EXAMINER	
OIL CONSERVATION DIVISION	
OCD	EXHIBIT NO. 46
CASE NO:	12758-A

Dear Sirs:

The following inspection(s) indicate one or more violations as described in the detail section below. The inspection(s) indicates that the well, equipment, location or operational status failed to meet standards of the New Mexico Oil Conservation Division. To comply with guidelines as established in the Division Rules and Regulations, corrective actions must be taken immediately and the situation brought into compliance. The detail section below indicates preliminary findings and/or probable nature of the violation. This is a subjective determination based on one or more factors of the results of the inspection.

Please notify the proper district office of the Division of the date corrective actions are scheduled and arrangements made so the well and/or facilities may be reinspected.

INSPECTION DETAIL SECTION

PEARSALL QUEEN SAND UNIT I-32-17S-32E 30-025-00795-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/08/2001	MIT Witnessed - Br	Johnny Robinson	Yes	No	8/31/2001	iSAD011033334

Comments on Inspection: No Well Sign. Well #11-1. Failed P.T.

PEARSALL QUEEN SAND UNIT 3-4-18S-32E 30-025-00838-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/08/2001	MIT Witnessed - Pr	Johnny Robinson	Yes	No	8/31/2001	iJDR011285698

Comments on Inspection: OK. All Equipment and Location in Good Shape. Violation due to shut in status and failed pressure test.

PEARSALL QUEEN SAND UNIT E-4-18S-32E 30-025-00839-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
-----------------	-----------------	-----------	------------	------------------------------	---------------------------	----------------

Witnessed - Pr Johnny Robinson Yes No 8/31/2001 iSAD011033337
Inspection: Equipment and Location needs minor attention. Failed well

ALL QUEEN SAND UNIT 1-5-18S-32E 30-025-00842-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/08/2001	MIT Witnessed - Pr	Johnny Robinson	Yes	No	8/31/2001	iSAD011033338
Comments on Inspection: OK. All Equipment and Location in Good Shape. Well # 3-1. Well is disconnected.						

PEARSALL QUEEN SAND UNIT I-5-18S-32E 30-025-00846-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/08/2001	MIT Witnessed - Pr	Johnny Robinson	Yes	No	8/31/2001	iSAD011033339
Comments on Inspection: Location needs attention. Equipment OK. Injection line is disconnected. Well # 9-1						

PEARSALL QUEEN SAND UNIT 3-5-18S-32E 30-025-00847-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/08/2001	MIT Witnessed - Pr	Johnny Robinson	Yes	No	8/31/2001	iSAD011033338
Comments on Inspection: Equipment and Location needs minor attention.						

PEARSALL QUEEN SAND UNIT G-5-18S-32E 30-025-00848-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/08/2001	MIT Witnessed - Pr	Johnny Robinson	Yes	No	8/31/2001	iSAD011033338
Comments on Inspection: Equipment and Location needs minor attention. Well number is (1-2).						

PEARSALL QUEEN SAND UNIT K-4-18S-32E 30-025-20242-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/08/2001	MIT Witnessed - Pr	Johnny Robinson	Yes	No	8/31/2001	iSAD011033337
Comments on Inspection: OK. All Equipment and Location in Good Shape. Failed well Wouldn't load.						

PEARSALL QUEEN SAND UNIT O-32-17S-32E 30-025-21711-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
05/08/2001	MIT Witnessed - Br	Johnny Robinson	Yes	No	8/31/2001	iSAD011033334
Comments on Inspection: Equipment and Location needs minor attention. No road to location. Failed well.						

prompt attention to this matter and your efforts in helping to protect our environment and the infrastructure and gas industry.



Williams, District I Supervisor

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.
*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.