




Pyote Well Service, LLC
Window Lake Com # 1
Essey County, NM
By: H. RICHMOND, GEOPHYSICIST

Exhibit No. 11
Case # 10-18
Date Filed 05/20/18
Pyote Well Service, LLC

Approx Lateral
TVD Depth

