31-Oct-07

Well Inspection History

API Number: 30-025-03035-00-00

Well Name & No.: STATE VC

Operator: SOUTHWESTERN INC, DWAYNE BURRIS

District: HOBBS

County Name: I FA

Field: STATE VC

Legal: S: 36 T: 17S R: 35E

Well Type: OII (PRODUCING)

0.2 ()						
Insp. Dt. Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
10/30/2007 File and Compliance Review	Status Check	iMGB0730352		119		

CHECKED LOCATION. I RECEIVED PHONE CALL FROM GAIL MACQUESTEN STATING THAT SOUTHWESTERN INC HAD CLEANED UP OILY SOIL AROUND TANKS. INSPECTION CONFIRMS THAT THE SOIL HAS BEEN REMOVED AND REPLACED WITH CLEAN SOIL. NO LEAKAGE FROM TANKS OBSERVE DURING INSPECTION. LEFT PHONE MESSAGE FOR GAIL 2:35 P.M. 10-30-2007. MGB.

PHOTOS TAKEN.

6/14/2007 Routine/Periodic

Status Check

iMGB0716536

ATTACH DO NOT OPERATE STICKER TO CONTROL PANEL. PUMPING UNIT--NATIONAL 456D, 2 BOLTED 500 BBL TANKS, 1 250 WELDED TANK, SEP, HORIZ. TREATER, 100 YDS =/- FLOWLINE, (LCEC #34532 ELEC METER).

6/13/2007 Routine/Periodic

Normal Routine Activity

i.ICW0716432

105

5/29/2007 Routine/Periodic

5/22/2007 Routine/Periodic

5/16/2007 Routine/Periodic

Normal Routine Activity

iMGB0714955

119

LETTER OF VIOLATION RETURNED IN THE MAIL. NOT DELIVERABLE, UNABLE TO FORWARD. Normal Routine Activity

iJCW0714227

105

5/18/2007 Phone call

Normal Routine Activity

iMGB0713856

119

PLACE 3 PHONE CALLS 11:14AM, 12:34PM, 2:43PM, NO ANSWER, BUSY EACH TIME.

Normal Routine Activity

iMGB0713649

119

100

103 114

Idle Well (Rule 201). NEED TO RETURN WELL TO PROD., T/A, OR P/A WELL. EQUIPMENT LEAKING (RULE 115), NEED TO REPAIR TANKS AND CLEANUP OIL CONTAMINATED SOIL. CONTACT LARRY JOHNSON FOR PLAN APPROVAL, PRIOR TO BEGINNING WORK, (505-393-6161 EXT 111, HOBBS-OCD). WELL SIGN (RULE 103) NEED TO REPLACE WELL SIGN, UNABLE TO READ OLD SIGN.

7/28/2005	Bradenhead
-----------	------------

iSAD05161400

114

OK. All Equipment and Location in Good Shape.

2/17/2005 Routine/Periodic

Normal Routine Activity

JDR05048353

113

Check well for production.

10/16/2002 Bradenhead Normal Routine Activity iJDR02289374

113

A-OK. All Equipment and Location in Good Shape.

7/11/2000 Bradenhead

7/10/2002 Routine/Periodic

Normal Routine Activity

iJDR02191339

113

Operator didn't show for BHT. Talked to SW yesterday about test. Called Dewayne and he couldn't find Glen Plemmons. I asked him to call in

and reschedule the test.

iSAD00173351

113

A-OK. All Equipment and Location in Good Shape.

iSAD0000787

106

6/24/1997 MIT Witnessed - Other

5/26/1999 MIT Witnessed - Other

unk0001578

102

6/18/1996 MIT Witnessed - Other

unk0001577

109

Total Inspections Performed: 15

Southwestern, Inc.

Case 14007 OCD Exhibit No. 7