16-Nov-07

3/30/2000 Routine/Periodic

Well Inspection History

API Number: 30-015-23516-00-00 Well Name & No.: HASTIE Operator: C&D MANAGEMENT COMPANY DBA FREE County Name: EDDY District: ARTESIA Field: HASTIE Legal: S: 18 T: 17S R: 28E Well Type: GAS (PRODUCING) Insp. Dt. Insp. Type Insp. Purpose Insp. No. RmdyRqDt Insp. By Viol. SNC 9/26/2007 Routine/Periodic iREH0726945 214 Normal Routine Activity PJ has been disconnected and moved to NW corner of location. Sucker rods still in hole. Flowlines connected to wellhead and lead to location off well site. Fresh dirt work has been conducted around wellhead area. New wellsign. 5/30/2007 File and Compliance Review Normal Routine Activity iMLB07150488 Spoke with company rep Tom Kaiser. He had his pumper call indicting contamination at well head area has been excavated and is ready for inspection. (Pumper is Larry Ivans: 365-4094) 2/14/2007 Routine/Periodic Normal Routine Activity iMLB07045504 211 Pumping unit and flowline intact. Electric supply switches are all in on poition. Timer switch is set to "auto". Pumping unit appears to have had recent operation. Contamination at wellhead reported on 9/28/06 inspection appears to have been covered with dirt and gravel. iPCH0627150 Normal Routine Activity oK. All Equipment and Location in Good Shape.(some contamination at wellhead) 2/14/2002 Routine/Periodic Normal Routine Activity iMLB02045488 211 A-OK. All Equipment and Location in Good Shape. PJ Leaking @ stuffing box. 9/18/2000 Routine/Periodic iGEG0026249 209 A-OK. All Equipment and Location in Good Shape. B

iPCH0000778

210

Total Inspections Performed: 7

Normal Routine Activity

A-OK. All Equipment and Location in Good Shape.

C & D Management Company dba Freedom Ventures Company Case 14055 OCD Exhibit No. 20