

28-Aug-08

Well Inspection History

API Number: **30-015-06125-00-00**

Well Name & No.: **WELCH DUKE STATE**

Operator: **SANDLOTT ENERGY (JACKIE BREWER DB)** District: **ARTESIA** County Name: **EDDY**

Field: **WELCH DUKE STATE**

Legal: **S: 28 T: 18S R: 28E**

Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
7/25/2007	Routine/Periodic	Normal Routine Activity	iMLB07206456		211		
Well appears capable of production. No indication of recent activity at well site. Contamination at well head area and out onto location.							
7/3/2006	File and Compliance Review	Normal Routine Activity	iPCH0618453		210		
Well appears capable of production. Older contamination at well head area and out onto location							
8/30/2005	Routine/Periodic	Normal Routine Activity	iMLB05242448		211		
Well appears capable of production. No indication of recent activity at well site. Older contamination at wellhead area and out onto location.							
10/15/2004	Routine/Periodic	Normal Routine Activity	iGEG0428930		209		
Location needs attention. Equipment OK.							
8/20/2004	Routine/Periodic	Normal Routine Activity	iGEG0423336		209		
Electricity off. Area contaminated.							
10/19/1999	Routine/Periodic	Status Check	iELG0003059		207		
Location needs attention. Equipment OK.							
10/19/1999	Routine/Periodic	Status Check	iELG0003058		207		
Location needs attention. Equipment OK.							
10/19/1999	Routine/Periodic	Status Check	iELG0002978		207		
A-OK. All Equipment and Location in Good Shape.							

Total Inspections Performed: 8

**Jackie Brewer D/B/A
Sandlott Energy
De Novo Case 14074
OCD Exhibit No. 14**