

11-Aug-09

Well Inspection History

API Number: **30-025-28576-00-00**

Well Name & No.: **POST**

Operator: **PLATINUM EXPLORATION INC, CONRAD T**

District: **HOBBS**

County Name: **LEA**

Field: **POST**

Legal: **S: 12 T: 14S R: 37E**

Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
8/6/2009	Phone call	Request/Complaint	iMGB0921854		119		
MR. GUY WILLIAMS CALLED AND SAID A ROUSTABOUT CREW AND VACUUM TRUCK HAD COME IN AND EMPTIED THE CELLAR AND THREW DIRT ON STANDING OIL AND LEFT. I TOLD HIM I WAS SCHEDULED TO FOLLOWUP ON MONDAY 8-10-2009.							
7/28/2009	Phone call	Normal Routine Activity	iMGB0920929		119		
CALL PLATINUM EXPLORATION, LEFT MESSAGE FOR ROBERT MCKENNZIE TO RETURN MY CALL IN REFERENCE TO LEAK AND CLEANUP. TIME OF CALL 8:10 AM LOCAL TIME. MR. MCKENNZIE RETURNED CALL AT 9:50 AM. DESCRIBED LEAK TO HIM AND HE SAID THAT HE WOULD SEND A GANG THAT WAY TO MAKE REPAIRS AND DO CLEANUP. MGB.							
7/27/2009	Compliance Verification	Status Check	iMGB0920859		119	Y	100 112 113
Idle Well (Rule 19.15.25.8). WELL IS STILL INACTIVE. MUST RETURN TO PRODUCTION, T/A OR P/A WELL. NEED TO INSTALL WELL SIGN, (RULE 19.15.16.8). OIL LEAKING FROM WELLHEAD MUST BE CORRECTED ASAP. SUBMIT C-141 FOR APPROVAL PRIOR TO CLEANUP. SUBMIT TO HOBBS DISTRICT 1 OFFICE, ATTENTION LARRY JOHNSON. (RULE 19.15.29.8). THIS IS 2ND LETTER OF NON-COMPLIANCE.							
6/24/2009	Routine/Periodic	Normal Routine Activity	iMGB0917559		119	Y	100 114 8
Idle Well (Rule 19.15.25.8) NEED TO RETURN TO PROD., T/A, OR P/A WELL. NO PROD REPORTED IN 46 MONTHS. ALSO NEED TO REMOVE OIL FROM CELLAR. RULE 19.15.29.8. CORRECT LEAK AND FILL IN CELLAR TO KEEP LIVESTOCK OUT. RULE 19.15.29.11. THIS IS 1ST LETTER OF NON-COMPLIANCE.							
6/23/2009	Routine/Periodic	Request/Complaint	iMGB0917455		119		
CHECK LOCATION. ONE SIDE OF CELLAR GRATING REMOVED, CELLAR CONTAINS LIQUIDS. PUMPING UNIT ON LOCATION, HORSE'S HEAD OFF UNIT. NO WELL SIGN. INSPECT T/B. GAS LEAKING FROM FLOWLINE, WATER STANDING INSIDE DIKE, ONE FIBERGLASS TANK HAS BEEN DESTROYED BY FIRE OR LIGHTING?. LAND OWNER--TODD ROERSON ON SITE. MGB.							
10/4/2001	Routine/Periodic	Normal Routine Activity	iBEP01277470	1/7/2002	111	Y	
Well appears to be SI, and idle check prod. No well sign							

Total Inspections Performed: 6

Case 14380

OCD Exhibit 10