

**From:** OILFREEDOM@aol.com  
**Sent:** Wednesday, April 01, 2009 4:38 PM  
**To:** Sanchez, Daniel J., EMNRD; Swazo, Sonny, EMNRD  
**Cc:** jerry\_blakley@nm.blm.gov  
**Subject:** C & D Management : April 9th Hearing -- Plugging of Wells  
**Attachments:** BLM Notice for CDM March 23, 2009.pdf; BLM OCD Letter to Sanchez OCD Blakley BLM.pdf

April 1, 2009

To: Mr. Swazo: - Mr. Sanchez

From: Thomas Kizer - C D Management Company

I have just learned, April 1st, while preparing paperwork for my April 9th that permits have been filed to plug various State and Federal wells.

Please be informed that the BLM has extended the date of April 30, 2009 to get these Federal wells into production [See Attached: Shearn Shilo - Saunders #12 - Scott Federal - Muncy 1/2]

It's my understanding that OCD/Artesia has requested permits for plugging of these Federal Well

**I request that you hold the disposition of these well in abeyance until the April 9th Hearing Date**

**Please contact OCD/Artesia to hold the Plugging of these wells**

**See attached letter & BLM**

---

Feeling the pinch at the grocery store? Make dinner for \$10 or less.

---

This inbound email has been scanned by the MessageLabs Email Security System.

---

*Case 14055 De Novo  
C&D Management Company  
dba Freedom Ventures Company  
OCD Exhibit 78*

3 pages

# C & D MANAGEMENT COMPANY

4801 Lang NE - Suite #110  
Albuquerque, NM 87109  
(505) 417-1511  
Email: oilfreedom@aol.com  
April 1, 2009

Via Facsimile: Bureau of Land Management - Carlsbad

Fax: (575) <sup>234 5927</sup>~~885-9264~~ - BLM/Carlsbad

Fax : 505-476-3462 - Daniel Sanchez, OCD/Santa Fe

To: James Amos & Jerry Blakley, Bureau of Land Management  
Daniel Sanchez, Oil Conservation Divison

Re: C D Management  
OCD Case No. 14055

I just spoke with Mike Bracher of the OCD/Artesia office and he has notified me that the following Federal wells are to be plugged.

I received Notice of the plugging of these wells on the OCD internet site today, April 1, 2009. I did not receive any written notice at our New Mexico office.

I have a Hearing on April 9, 2009 with the OCD.

I request that disposition of the Federal Wells be held in abeyance until the April 9<sup>th</sup> hearing in Santa Fe. {Case

The wells in question are:

Saunder #12: 30-015-22348 [Federal]

This is a gas well that has been producing and manifests production in Amoco Meter. Jerry Blakley indicated that separate meter has to be installed on this well. There is currently a 'graph reading on the well.

Scott Federal: 30-015-25437 [Federal]

We activated this well in November and it has produced both water and oil.

Shearn Shilo 30-015-31061 [Federal]

This was a well drilled by JKM Energy and was ordered to plugged by OCD. There were obstacles in the well that prevented plugging. We have received an extension from the BLM to plug this well.

Muncy Wells 30-015-23083 -- 30-015-25012: [Federal]

These wells have been dormant. We were scheduling to pull the tubing and re work these wells.

Schneider: 30-015-22907 [State Well]

According to Bratcher the well is being plugged as of March 30, 2009.

Thomas Kizer

# I & E CFO

**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT**

**NOTICE OF WRITTEN ORDER**

Certified Mail - Return Receipt Requested  
70081830000080712429

IDENTIFICATION	
IID	
Lease	NMNM02931
CA	
Unit	
PA	

Bureau of Land Management Office <b>CARLSBAD FIELD OFFICE</b>		Operator <b>C &amp; D MANAGEMENT COMPANY</b>					
Address <b>620 E GREENE STREET CARLSBAD NM 88220</b>		Address <b>4801 LANGE NE, SUITE 110 ALBUQUERQUE NM 87109</b>					
Telephone <b>575-234-5994</b>		Attention					
Inspector <b>BLAKLEY</b>		Attn Addr					
Site Name <b>MUNCY FEDERAL</b>	Well or Facility <b>1</b>	1/4 1/4 Section <b>SEW 13</b>	Township <b>17S</b>	Range <b>27E</b>	Meridian <b>NMP</b>	County <b>EDDY</b>	State <b>NM</b>
Site Name	Well or Facility	1/4 1/4 Section	Township	Range	Meridian	County	State
Site Name	Well or Facility	1/4 1/4 Section	Township	Range	Meridian	County	State

The following condition(s) were found by Bureau of Land Management Inspectors on the date and at the site(s) listed above.

Date	Time (24-hour clock)	Corrective Action to be Completed by	Date Corrected	Authority Reference
03/20/2009	13:00	04/30/2009		43 CFR 3162.3-4(a),(b),(c) and 43 CFR 3162.1(a)

Remarks:

OUR RECORDS INDICATE THAT THE ABOVE WELL IS SHUT-IN (SI) OR TEMPORARILY ABANDONED (TA). THE BUREAU OF LAND MANAGEMENT (BLM) AND MINERALS MANAGEMENT SERVICE (MMS) DEFINITION OF A SHUT-IN WELL IS A COMPLETION THAT IS PHYSICALLY AND MECHANICALLY CAPABLE OF PRODUCTION IN PAYING QUANTITIES OR CAPABLE OF SERVICE USE. THE DEFINITION OF A TEMPORARILY ABANDONED WELL IS A COMPLETION THAT IS NOT CAPABLE OF PRODUCTION IN PAYING QUANTITIES BUT WHICH MAY HAVE VALUE AS A SERVICE COMPLETION. ACCORDING TO OUR RECORDS THE WELL REFERENCED ABOVE HAS BEEN SHUT-IN OR HAS BEEN TEMPORARILY ABANDONED WITHOUT AUTHORIZATION. 43 CFR 3162.3-4 (C) REQUIRES THAT WELLS INCAPABLE OF PRODUCTION IN PAYING QUANTITIES BE PROMPTLY PLUGGED AND ABANDONED AND REQUIRES APPROVAL FOR ANY WELL TEMPORARILY ABANDONED FOR MORE THAN 30 DAYS.  
Remarks continued on following page(s).

When the Written Order is complied with, sign this notice and return to above address.

Company Representative Title \_\_\_\_\_ Signature \_\_\_\_\_ Date \_\_\_\_\_  
Company Comments \_\_\_\_\_

**Warning**

The Authorized Officer has authority to issue a Written Order in accordance with 43 CFR 3161.2. Written Order correction and reporting time frames begin upon receipt of this Notice or 7 business days after the date it is mailed, whichever is earlier. Each stipulation must be corrected within the prescribed time from receipt of this Notice reported to the Bureau of Land Management Office at the address shown above. If you do not comply as noted above under "Corrective Action to be Completed" shall be issued an Incident of Noncompliance (INC) in accordance with 43 CFR 3163.1(a). Failure to comply with the INC may result in assessments as outlined in 43 CFR 3163.1 and may also incur civil penalties (43 CFR 3163.2). All self-certified corrections must be postmarked no later than the next business day after the prescribed time frame for correction.

Section 109(d)(1) of the Federal Oil and Gas Royalty Management Act of 1982, as implemented by the applicable provisions of the operating regulations at Title 43 CFR 3163.2(f)(1), provides that any person who "knowingly or willfully" prepares, maintains, or submits false, inaccurate, or misleading reports, notices, affidavits, records or other written information required by this part shall be liable for a civil penalty of up to \$25,000 per violation for each day such violation continues, not to exceed a maximum of 20 days.

**Review and Appeal Rights**

A person contesting a decision shall request a State Director review of the Written Order. This request must be filed within 20 working days of receipt of the Notice of the appropriate State Director (see 43 CFR 3165.3). The State Director review decision may be appealed to the Interior Board of Land Appeals, 801 North Quincy Street, Suite 300, Arlington, VA 22203 (see 43 CFR 3165.4). Contact the above listed Bureau of Land Management office for further information.

Signature of Bureau of Land Management Authorized Officer \_\_\_\_\_ Date 3/23/09 Time 1300

# I & E CFO

Certified Mail - Return Receipt Requested  
7008183000080712429

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

IDENTIFICATION	
IID	
Lease	NMNM02931
CA	
Unit	
PA	

## NOTICE OF WRITTEN ORDER

Bureau of Land Management Office <b>CARLSBAD FIELD OFFICE</b>				Operator <b>C &amp; D MANAGEMENT COMPANY</b>			
Address <b>620 E GREENE STREET CARLSBAD NM 88220</b>				Address <b>4801 LANGE NE, SUITE 110 ALBUQUERQUE NM 87109</b>			
Telephone <b>575-234-5994</b>				Attention <b>C &amp; D MANAGEMENT COMPANY</b>			
Inspector <b>BLAKLEY</b>				Attn Addr <b>4801 LANGE NE, SUITE 110 ALBUQUERQUE NM 87109</b>			
Site Name <b>MUNCY FEDERAL</b>	Well or Facility <b>2</b>	1/4 1/4 Section <b>SWNW 13</b>	Township <b>17S</b>	Range <b>27E</b>	Meridian <b>NMP</b>	County <b>EDDY</b>	State <b>NM</b>
Site Name	Well or Facility	1/4 1/4 Section	Township	Range	Meridian	County	State
Site Name	Well or Facility	1/4 1/4 Section	Township	Range	Meridian	County	State

The following condition(s) were found by Bureau of Land Management Inspectors on the date and at the site(s) listed above.

Date	Time (24-hour clock)	Corrective Action to be Completed by	Date Corrected	Authority Reference
03/20/2009	13:00	04/30/2009		43 CFR 3162.3-4(a),(b),(c) and 43 CFR 3162.1(a)

Remarks:  
OUR RECORDS INDICATE THAT THE ABOVE WELL IS SHUT-IN (SI) OR TEMPORARILY ABANDONED (TA). THE BUREAU OF LAND MANAGEMENT (BLM) AND MINERALS MANAGEMENT SERVICE (MMS) DEFINITION OF A SHUT-IN WELL IS A COMPLETION THAT IS PHYSICALLY AND MECHANICALLY CAPABLE OF PRODUCTION IN PAYING QUANTITIES OR CAPABLE OF SERVICE USE. THE DEFINITION OF A TEMPORARILY ABANDONED WELL IS A COMPLETION THAT IS NOT CAPABLE OF PRODUCTION IN PAYING QUANTITIES BUT WHICH MAY HAVE VALUE AS A SERVICE COMPLETION. ACCORDING TO OUR RECORDS THE WELL REFERENCED ABOVE HAS BEEN SHUT-IN OR HAS BEEN TEMPORARILY ABANDONED WITHOUT AUTHORIZATION. 43 CFR 3162.3-4 (C) REQUIRES THAT WELLS INCAPABLE OF PRODUCTION IN PAYING QUANTITIES BE PROMPTLY PLUGGED AND ABANDONED AND REQUIRES APPROVAL FOR ANY WELL TEMPORARILY ABANDONED FOR MORE THAN 30 DAYS.  
(Remarks continued on following page(s).)

When the Written Order is complied with, sign this notice and return to above address.

Company Representative Title \_\_\_\_\_ Signature \_\_\_\_\_ Date \_\_\_\_\_  
Company Comments \_\_\_\_\_

### Warning

The Authorized Officer has authority to issue a Written Order in accordance with 43 CFR 3161.2. Written Order correction and reporting time frames begin upon receipt of this Notice or 7 business days after the date it is mailed, whichever is earlier. Each stipulation must be corrected within the prescribed time from receipt of this Notice and reported to the Bureau of Land Management Office at the address shown above. If you do not comply as noted above under "Corrective Action to be Completed by", you shall be issued an Incident of Noncompliance (INC) in accordance with 43 CFR 3163.1(a). Failure to comply with the INC may result in assessments as outlined in 43 CFR 3163.1 and may also incur civil penalties (43 CFR 3163.2). All self-certified corrections must be postmarked no later than the next business day after the prescribed time frame for correction.

Section 109(d)(1) of the Federal Oil and Gas Royalty Management Act of 1982, as implemented by the applicable provisions of the operating regulations at Title 43 CFR 3163.2(f)(1), provides that any person who "knowingly or willfully" prepares, maintains, or submits false, inaccurate, or misleading reports, notices, affidavits, records, data, or other written information required by this part shall be liable for a civil penalty of up to \$25,000 per violation for each day such violation continues, not to exceed a maximum of 20 days.

### Review and Appeal Rights

A person contesting a decision shall request a State Director review of the Written Order. This request must be filed within 20 working days of receipt of the Notice with the appropriate State Director (see 43 CFR 3165.3). The State Director review decision may be appealed to the Interior Board of Land Appeals, 801 North Quiney Street, Suite 300, Arlington, VA 22203 (see 43 CFR 3165.4). Contact the above listed Bureau of Land Management office for further information.

Signature of Bureau of Land Management Authorized Officer <i>[Signature]</i>		Date <i>3/23/09</i>	Time <i>1300</i>
FOR OFFICE USE ONLY			
Number <b>51</b>	Date	Type of Inspection <b>PI</b>	



Certified Mail - Return Receipt Requested  
70081830060080712429

**DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT**

IDENTIFICATION	
ID	
Lease	NMLCC64023
CA	
Unit	
PA	

**NOTICE OF WRITTEN ORDER**

Bureau of Land Management Office <b>CARLSBAD FIELD OFFICE</b>	Operator <b>C &amp; D MANAGEMENT COMPANY</b>
Address <b>620 E GREENE STREET CARLSBAD NM 88220</b>	Address <b>4801 LANGE NE, SUITE 110 ALBUQUERQUE NM 87109</b>
Telephone <b>575-234-5994</b>	Attention
Inspector <b>BLAKLEY</b>	Attn Addr

Site Name <b>SAUNDERS</b>	Well or Facility <b>12</b>	1/4 1/4 Section <b>SWSE 13</b>	Township <b>17S</b>	Range <b>27E</b>	Meridian <b>NMP</b>	County <b>EDDY</b>	State <b>NM</b>
Site Name	Well or Facility	1/4 1/4 Section	Township	Range	Meridian	County	State
Site Name	Well or Facility	1/4 1/4 Section	Township	Range	Meridian	County	State

The following condition(s) were found by Bureau of Land Management Inspectors on the date and at the site(s) listed above.

Date	Time (24-hour clock)	Corrective Action to be Completed by	Date Corrected	Authority Reference
03/20/2009	13:00	04/30/2009		43 CFR 3162.3-4(a),(b),(c) and 43 CFR 3162.1(a)

Remarks:  
OUR RECORDS INDICATE THAT THE ABOVE WELL IS SHUT-IN (SI) OR TEMPORARILY ABANDONED (TA). THE BUREAU OF LAND MANAGEMENT (BLM) AND MINERALS MANAGEMENT SERVICE (MMS) DEFINITION OF A SHUT-IN WELL IS A COMPLETION THAT IS PHYSICALLY AND MECHANICALLY CAPABLE OF PRODUCTION IN PAYING QUANTITIES OR CAPABLE OF SERVICE USE. THE DEFINITION OF A TEMPORARILY ABANDONED WELL IS A COMPLETION THAT IS NOT CAPABLE OF PRODUCTION IN PAYING QUANTITIES BUT WHICH MAY HAVE VALUE AS A SERVICE COMPLETION. ACCORDING TO OUR RECORDS THE WELL REFERENCED ABOVE HAS BEEN SHUT-IN OR HAS BEEN TEMPORARILY ABANDONED WITHOUT AUTHORIZATION. 43 CFR 3162.3-4 (C) REQUIRES THAT WELLS INCAPABLE OF PRODUCTION IN PAYING QUANTITIES BE PROMPTLY PLUGGED AND ABANDONED AND REQUIRES APPROVAL FOR ANY WELL TEMPORARILY ABANDONED FOR MORE THAN 30 DAYS.  
(Remarks continued on following page(s).)

When the Written Order is complied with, sign this notice and return to above address.

Company Representative Title: \_\_\_\_\_ Signature: \_\_\_\_\_ Date: \_\_\_\_\_

Company Comments: \_\_\_\_\_

**Warning**

The Authorized Officer has authority to issue a Written Order in accordance with 43 CFR 3161.2. Written Order correction and reporting time frames begin upon receipt of this Notice or 7 business days after the date it is mailed, whichever is earlier. Each stipulation must be corrected within the prescribed time from receipt of this Notice and reported to the Bureau of Land Management Office at the address shown above. If you do not comply as noted above under "Corrective Action to be Completed By", you shall be issued an Incident of Noncompliance (INC) in accordance with 43 CFR 3163.1(a). Failure to comply with the INC may result in assessments as outlined in 43 CFR 3163.1 and may also incur civil penalties (43 CFR 3163.2). All self-certified corrections must be postmarked no later than the next business day after the prescribed time frame for correction.

Section 109(d)(1) of the Federal Oil and Gas Royalty Management Act of 1982, as implemented by the applicable provisions of the operating regulations at Title 43 CFR 3163.2(f)(1), provides that any person who "knowingly or willfully" prepares, maintains, or submits false, inaccurate, or misleading reports, notices, affidavits, records, data, or other written information required by this part shall be liable for a civil penalty of up to \$25,000 per violation for each day such violation continues, not to exceed a maximum of 20 days.

**Review and Appeal Rights**

A person contesting a decision shall request a State Director review of the Written Order. This request must be filed within 20 working days of receipt of the Notice with the appropriate State Director (see 43 CFR 3165.3). The State Director review decision may be appealed to the Interior Board of Land Appeals, 801 North Quincy Street, Suite 300, Arlington, VA 22203 (see 43 CFR 3165.4). Contact the above listed Bureau of Land Management office for further information.

Signature of Bureau of Land Management Authorized Officer <i>[Signature]</i>	Date <b>3/23/09</b>	Time <b>13:00</b>
<b>FOR OFFICE USE ONLY</b>		
Number <b>51</b>	Date	Type of Inspection <b>PI</b>



Certified Mail - Return Receipt Requested  
7008183000080712429

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

IDENTIFICATION	
IID	
Lease	NMNM41655
CA	
Unit	
PA	

NOTICE OF WRITTEN ORDER

Bureau of Land Management Office <b>CARLSBAD FIELD OFFICE</b>	Operator <b>C &amp; D MANAGEMENT COMPANY</b>
Address <b>620 E GREENE STREET CARLSBAD NM 88220</b>	Address <b>4801 LANGE NE, SUITE 110 ALBUQUERQUE NM 87109</b>
Telephone <b>575-234-5994</b>	Attention
Inspector <b>BLAKLEY</b>	Attn Addr

Site Name <b>SCOTT FEDERAL</b>	Well or Facility <b>1</b>	1/4 1/4 Section <b>SESE 12</b>	Township <b>17S</b>	Range <b>27E</b>	Meridian <b>NMP</b>	County <b>EDDY</b>	State <b>NM</b>
Site Name <b>SCOTT FED.</b>	Well or Facility <b>L</b>	1/4 1/4 Section <b>SESE 12</b>	Township <b>17S</b>	Range <b>27E</b>	Meridian <b>NMP</b>	County <b>EDDY</b>	State <b>NM</b>
Site Name	Well or Facility	1/4 1/4 Section	Township	Range	Meridian	County	State

The following condition(s) were found by Bureau of Land Management Inspectors on the date and at the site(s) listed above.

Date	Time (24-hour clock)	Corrective Action to be Completed by	Date Corrected	Authority Reference
03/20/2009	13:00	04/30/2009		43 CFR 3162.3-4(a),(b),(c) and 43 CFR 3162.1(a)

Remarks:  
OUR RECORDS INDICATE THAT THE ABOVE WELL IS SHUT-IN (SI) OR TEMPORARILY ABANDONED (TA). THE BUREAU OF LAND MANAGEMENT (BLM) AND MINERALS MANAGEMENT SERVICE (MMS) DEFINITION OF A SHUT-IN WELL IS A COMPLETION THAT IS PHYSICALLY AND MECHANICALLY CAPABLE OF PRODUCTION IN PAYING QUANTITIES OR CAPABLE OF SERVICE USE. THE DEFINITION OF A TEMPORARILY ABANDONED WELL IS A COMPLETION THAT IS NOT CAPABLE OF PRODUCTION IN PAYING QUANTITIES BUT WHICH MAY HAVE VALUE AS A SERVICE COMPLETION. ACCORDING TO OUR RECORDS THE WELL REFERENCED ABOVE HAS BEEN SHUT-IN OR HAS BEEN TEMPORARILY ABANDONED WITHOUT AUTHORIZATION. 43 CFR 3162.3-4 (C) REQUIRES THAT WELLS INCAPABLE OF PRODUCTION IN PAYING QUANTITIES BE PROMPTLY PLUGGED AND ABANDONED AND REQUIRES APPROVAL FOR ANY WELL TEMPORARILY ABANDONED FOR MORE THAN 30 DAYS.  
(Remarks continued on following page(s).)

When the Written Order is complied with, sign this notice and return to above address.

Company Representative Title \_\_\_\_\_ Signature \_\_\_\_\_ Date \_\_\_\_\_  
Company Comments \_\_\_\_\_

Warning

The Authorized Officer has authority to issue a Written Order in accordance with 43 CFR 3161.2. Written Order correction and reporting time frames begin upon receipt of this Notice or 7 business days after the date it is mailed, whichever is earlier. Each stipulation must be corrected within the prescribed time from receipt of this Notice and reported to the Bureau of Land Management Office at the address shown above. If you do not comply as noted above under "Corrective Action to be Completed By", you shall be issued an Incident of Noncompliance (INC) in accordance with 43 CFR 3163.1(a). Failure to comply with the INC may result in assessments as outlined in 43 CFR 3163.1 and may also incur civil penalties (43 CFR 3163.2). All self-certified corrections must be postmarked no later than the next business day after the prescribed time frame for correction.

Section 109(d)(1) of the Federal Oil and Gas Royalty Management Act of 1982, as implemented by the applicable provisions of the operating regulations at Title 43 CFR 3163.2(f)(1), provides that any person who "knowingly or willfully" prepares, maintains, or submits false, inaccurate, or misleading reports, notices, affidavits, records, data, or other written information required by this part shall be liable for a civil penalty of up to \$25,000 per violation for each day such violation continues, not to exceed a maximum of 20 days.

Review and Appeal Rights

A person contesting a decision shall request a State Director review of the Written Order. This request must be filed within 20 working days of receipt of the Notice with the appropriate State Director (see 43 CFR 3165.3). The State Director review decision may be appealed to the Interior Board of Land Appeals, 801 North Quincy Street, Suite 300, Arlington, VA 22203 (see 43 CFR 3165.4). Contact the above listed Bureau of Land Management office for further information.

Signature of Bureau of Land Management Authorized Officer <i>[Signature]</i>	Date <i>3/23/09</i>	Time <i>13:00</i>
FOR OFFICE USE ONLY		
Number <b>51</b>	Date	Type of Inspection <b>PI</b>

# I & E CFO

Form 3260-18  
(October, 1999)

Number 09JB025W

Page of

Certified Mail - Return Receipt Requested  
70081830000080712429

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

IDENTIFICATION	
IID	
Lease	NMNM02931
CA	
Unit	
PA	

## NOTICE OF WRITTEN ORDER

Bureau of Land Management Office <b>CARLSBAD FIELD OFFICE</b>				Operator <b>C &amp; D MANAGEMENT COMPANY</b>			
Address <b>620 E GREENE STREET CARLSBAD NM 88220</b>				Address <b>4801 LANGE NE, SUITE 110 ALBUQUERQUE NM 87109</b>			
Telephone <b>575-234-5994</b>				Attention <b>C &amp; D MANAGEMENT COMPANY</b>			
Inspector <b>BLAKLEY</b>				Attn Addr <b>4801 LANGE NE, SUITE 110 ALBUQUERQUE NM 87109</b>			
Site Name <b>MUNCY FEDERAL</b>	Well or Facility <b>2</b>	1/4 1/4 Section <b>SWNW 13</b>	Township <b>17S</b>	Range <b>27E</b>	Meridian <b>NMP</b>	County <b>EDDY</b>	State <b>NM</b>
Site Name	Well or Facility	1/4 1/4 Section	Township	Range	Meridian	County	State
Site Name	Well or Facility	1/4 1/4 Section	Township	Range	Meridian	County	State

The following condition(s) were found by Bureau of Land Management Inspectors on the date and at the site(s) listed above.

Date	Time (24-hour clock)	Corrective Action to be Completed by	Date Corrected	Authority Reference
03/20/2009	13:00	04/30/2009		43 CFR 3162.3-4(a),(b),(c) and 43 CFR 3162.1(a)

Remarks:  
OUR RECORDS INDICATE THAT THE ABOVE WELL IS SHUT-IN (SI) OR TEMPORARILY ABANDONED (TA). THE BUREAU OF LAND MANAGEMENT (BLM) AND MINERALS MANAGEMENT SERVICE (MMS) DEFINITION OF A SHUT-IN WELL IS A COMPLETION THAT IS PHYSICALLY AND MECHANICALLY CAPABLE OF PRODUCTION IN PAYING QUANTITIES OR CAPABLE OF SERVICE USE. THE DEFINITION OF A TEMPORARILY ABANDONED WELL IS A COMPLETION THAT IS NOT CAPABLE OF PRODUCTION IN PAYING QUANTITIES BUT WHICH MAY HAVE VALUE AS A SERVICE COMPLETION. ACCORDING TO OUR RECORDS THE WELL REFERENCED ABOVE HAS BEEN SHUT-IN OR HAS BEEN TEMPORARILY ABANDONED WITHOUT AUTHORIZATION. 43 CFR 3162.3-4 (C) REQUIRES THAT WELLS INCAPABLE OF PRODUCTION IN PAYING QUANTITIES BE PROMPTLY PLUGGED AND ABANDONED AND REQUIRES APPROVAL FOR ANY WELL TEMPORARILY ABANDONED FOR MORE THAN 30 DAYS.  
(Remarks continued on following page(s).)

When the Written Order is complied with, sign this notice and return to above address.

Company Representative Title \_\_\_\_\_ Signature \_\_\_\_\_ Date \_\_\_\_\_

Company Comments \_\_\_\_\_


### Warning

The Authorized Officer has authority to issue a Written Order in accordance with 43 CFR 3161.2. Written Order correction and reporting time frames begin upon receipt of this Notice or 7 business days after the date it is mailed, whichever is earlier. Each stipulation must be corrected within the prescribed time from receipt of this Notice and reported to the Bureau of Land Management Office at the address shown above. If you do not comply as noted above under "Corrective Action to be Completed By", you shall be issued an Incident of Noncompliance (INC) in accordance with 43 CFR 3163.1(a). Failure to comply with the INC may result in assessments as outlined in 43 CFR 3163.1 and may also incur civil penalties (43 CFR 3163.2). All self-certified corrections must be postmarked no later than the next business day after the prescribed time frame for correction.

Section 109(d)(1) of the Federal Oil and Gas Royalty Management Act of 1982, as implemented by the applicable provisions of the operating regulations at Title 43 CFR 3163.2(f)(1), provides that any person who "knowingly or willfully" prepares, maintains, or submits false, inaccurate, or misleading reports, notices, affidavits, records, data, or other written information required by this part shall be liable for a civil penalty of up to \$25,000 per violation for each day such violation continues, not to exceed a maximum of 20 days.

### Review and Appeal Rights

A person contesting a decision shall request a State Director review of the Written Order. This request must be filed within 20 working days of receipt of the Notice with the appropriate State Director (see 43 CFR 3165.3). The State Director review decision may be appealed to the Interior Board of Land Appeals, 801 North Quincy Street, Suite 300, Arlington, VA 22203 (see 43 CFR 3165.4). Contact the above listed Bureau of Land Management office for further information.

Signature of Bureau of Land Management Authorized Officer 		Date <b>3/23/09</b>	Time <b>1300</b>
FOR OFFICE USE ONLY			
Number <b>51</b>	Date	Type of Inspection <b>PI</b>	