

Bravo Dome Carbon Dioxide Gas Unit Information Sheet

- Porosity - 12% to 30%
- Permeability - Average 5 - 40 md
- Gross Pay thickness - 50' to 250'
- Current well spacing - 640 acre
- Water Saturation - 30%
- Active wells - 350
- Number of main trunk gathering lines 9

Amoco/Bravo Dome/NMOCC

BEFORE THE
OIL CONSERVATION DIVISION
Santa Fe, New Mexico

Case No. 11497 Exhibit No. 10

Submitted by: Amoco Production Company

Hearing Date: March 21, 1996