




- Oil Producer
 - ☀ Gas Producer
 - ☼ Dry Hole
 - ☼ Plugged And Abandoned
 - Temporarily Abandoned/Inactive
- 253 Cumulative Morrow Production**
- Only deep gas penetrations shown*

Perforated in Lower B

**BEFORE THE
OIL CONSERVATION COMMISSION**

Case No. 11985 Exhibit No. 4
Submitted By:

OXY USA, Inc.

1998

WINCHESTER FIELD
Eddy Co., New Mexico

Eddy Co., New Mexico

NET PAY

Geol: R.L. Doty

C.I. = 10 ft.

Date: 7/6/1998

Feet