


R14W



0 1 kms miles
CONTOUR INTERVAL: 25 Feet



Down-to-North Fault



Down-to-South Fault



Active Dakota Producing Well



Cross Timbers Oil Company

UTE DOME FIELD

San Juan County, New Mexico

STRUCTURE: Top of Dakota

November, 1998

GKB/MSV

NEW MEXICO
C.I.L. CONSERVATION DIVISION

EXHIBIT 2

CASE NO. _____