

⊙	LRIC / Capataz Location
●	Blinebry Producer
△	Tested Non Commercial this Zone
N	Not Deep Enough
NA	Not Available
NLTI	No Log this Interval
NØL	No Porosity Log
NL	Not Logged

LRIC / CAPATAZ OPERATING

MARSHALL #1

Lea County, New Mexico and Gaines County, Texas

ISOPACH MAP
BLINEBRY DOLOMITE (P-1) POROSITY

Feet of Dolomite ≥ 10% Porosity

Contour Interval = 10'

Date: May, 2001

Geology by: John Worrall

OIL CONSERVATION DIVISION

CASE NUMBER _____

EXHIBIT 4