

EI Paso Natural Gas Products Company
Case No. . 1596
Exhibit No. 12
Date February 18, 1959

HORSESHOE GALLUP FIELD
SAN JUAN COUNTY, NEW MEXICO
BOTTOM HOLE PRESSURES SANDS "A" AND "B"

Operator	:	Location	:	Survey	:	Shut-In Time	:	BHP	:	Remarks
Lease	:	Well No.	:	1/4 1/4 Sec. - Twn-Rng	:	Date	:	Hours	:	* Sand "A" : ** Sand "B" : *** Sand "B" :
El Paso Natural Gas Products Co.										
Horseshoe Canyon	1	NE SE	4-30-16	2-8-59	72	238	201	Natural Completion		
Horseshoe Canyon	4	SE SW	3-30-16	11-1-57	48	243	209	Natural Completion		
								Initial BHP Survey		
Horseshoe Canyon	6	NW NW	10-30-16	1-28-59	43	194		Sandoll Fractured		
Horseshoe Canyon	8	NE SW	4-30-16	1-29-59	192	180		Sandoll Fractured		
Horseshoe Canyon	2-B	NE NW	4-30-16	9-24-57	49	276	243	Natural Completion		
				10-4-57	48	221		Initial BHP Surveys		

Gradient 0.335 psi/ft.

* Datum / 4175'
** Datum / 4075'
*** Datum / 4175'