


(SUBMIT IN TRIPLICATE)

Land Office **Las Cruces**
Lease No. **02427**
Unit _____



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Notice of Intention to Inject Water	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 3, 19**59**


Well No. **Etz E 2** is located **1980** ft. from **N** line and **660** ft. from **E** line of sec. **34**
SE/4 NE/4 of 34 **16 South 30 East** **N.M.P.M.**
($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Square Lake **Eddy County** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well has been cleaned to total depth of 3160 feet and casing tested to 2500 pounds for the purpose of injection of water obtained from the shallow sands above 400 feet into the Grayburg formation at the approximate depth of 3085 feet and the San Andres formation at the approximate depth of 3146 feet.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Texas Consolidated Oils, Incorporated**

Address **Box 955**

Andrews, Texas

By **W. Randolph Reese**
Title **Attorney**