

EPNG PRESSURE BUILD-UP TEST

TEST WELL DATA Basin Dakota Pool

Date Feb. 5, 1963

TEST WELL: Operator: El Paso Natural Gas Company Well Name & No. Allison Unit No. 1

Location 1980 fr. N, 660 fr. W lines, E Sec. 17 T. 32 N., R. 6 W

TD: 8660 Casing: 7930 Tubing: 8022

Completed: 8/30/54 Reworked 2/13/59 First Delivery: 2/2/55

Pay Zone: Open Hole Interval: 7930-8084 or Perforations:

Stimulation: Sand-Oil Frac

SIPC: 2897 SIPT: 2869 DAYS SI: 14

I. P. Test: 2326 MCF, 3 hrs. 3/4" Choke: - MCF AOF thru tubing or casing

Current Deliverability: 449 MCF, Date Tested: 1962

WELLS ON SAME BASIC LEASE

<u>Name</u>	<u>Location</u>	<u>Deliverability</u>	<u>Date of Test</u>
Allison Unit #20	L-18-32-6	1397	1962
Allison Unit #23-X	M-19-32-6	679	1962

SAN JUAN COUNTY, NEW MEXICO

BASIN DAKOTA

TOWNSHIP 32-N RANGE 6-W

