




STRUCTURAL WELLBORE DIAGRAMS
TOP OF M1 SAND
C-115 PRODUCTION
3 MONTH AVERAGE
EAST LOYING DE ~~BEFORE THE~~ D

OIL CONSERVATION COMMISSION
Santa Fe, New Mexico


Case No. 10226 Exhibit No. 6

Submitted by BIRD CREEK

Hearing Date 8-29-91

WEST

EAST




D'

SOUTH


D

NORTH





E

E



0.1° incline






WEST

H

EAST

H



0.6° incline

Current Production