



OIL CONSERVATION DIVISION  
RECEIVED

'93 DE 128 AM 9 11

December 27, 1993

Oil Conservation Division  
P. O. Box 2088  
Santa Fe, New Mexico 87504-2088

Attention: Mr. Michael Stogner

RE: Consolidation Glorietta  
Yeso Formation into  
Burch Keely Unit  
Loco Hills Area  
Eddy County, New Mexico

Dear Mr. Stogner:

Enclosed please find copies of the logs on Burch Keely Unit #210 (Kelly A #30) and Burch Keely Unit #211 (Burch C #49). I have marked our reported geologic tops and the lower tested perforations. Also enclosed is a copy of the bottom hole pressure tests which were run after the formation had been treated with acid and flowed back. I have also included the following maps:

- 1.) Proration units of the Grayburg Jackson field and the Square Lake field in the same area.
- 2.) Injection wells in the Grayburg Jackson field and Square Lake field in the same area.
- 3.) Units in the same general area as the Burch Keely Unit.

If after reviewing this information, you have any additional questions, please contact me.

Sincerely,  
*Raye Miller*  
Raye Miller  
Land Department

RM/mm  
Enclosures

cc: Mr. Bill LeMay  
Oil Conservation Division  
P. O. Box 2088  
Santa Fe, New Mexico 87504-2088

cc: Mr. Jim Morrow  
Oil Conservation Division  
P. O. Box 2088  
Santa Fe, New Mexico 87504-2088

cc: Mr. Bill Carr  
Campbell, Carr, Berge, Sheridan  
P. O. Box 2208  
Santa Fe, New Mexico 87504-2208