

WATER ANALYSIS - HALLIBURTON SERVICES

Located NW/4 of SW/4 of Section 29, T-14-S,
R-34-E, Lea County, New Mexico.

Res. at 70° = 5.41 ohms

G. S. = 1.000

PL = 7.8

Ca ++ = 100 ppm

Ma ++ = 100 ppm

CI - = 75 ppm

SO₄ -- = 70 ppm

Bicarb = 168 ppm

Fe = None

513 ppm

BEFORE EXAMINER SIGNATURE

Oil Conservation Division

Exam. No. J

Case No. 9825+9826