

BEFORE EXAMINER CATANACH



OIL CONSERVATION DIVISION

EXHIBIT NO. 32

CASE NO. 11956

Chaco 1, Fracture Dimensions


Stress Profile




CHACO #1 PETCOM 13

9 Jun 1998 @ 15:34

DEPTH (FT)



*Black-
No + Analyzed
May be
a coal*



A
B
C
D
E