

BEFORE EXAMINER CATANACH

OIL CONSERVATION DIVISION

33



EXHIBIT NO.

11996

CASE NO.

Chaco 4, Fracture Dimensions

Stress Profile



CHACO #4 PETCOM 11

3 Jun 1998 @ 14:45

DEPTH (FT)

