

Division 1
1621 N. French Dr., Hobbs, NM 88240
Phone: (505) 397-6181 Fax: (505) 397-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name BXP Operating, LLC	API Number 30-015-04562
Property Name North Benson Queen Unit	Well No. 39

Surface Location									
UL - Lot F	Section 34	Township 18S	Range 30E		Feet from 1650	NS Line N	Feet from 1980	E/W Line W	County EDDY

Well Status									
YES	T&D WELL ☐ NO	YES	SHUT-IN ☐ NO	☒ INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 6-18-2020

OBSERVED DATA

	(A) Surface	(B) Intern (1)	(C) Intern (2)	(D) Prod Cmk	(E) Tubing
Pressure	0			0	760
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 WTR ☒ GAS ☐ Type of fluid is listed for wellhead if applies
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>M. Y. Merchant</i>	OIL CONSERVATION DIVISION
Printed name: M. Y. Merchant	Entered into RBDMS
Title: Production Supervisor	Re-test
E-mail Address: mymerch@penrocoil.com	Accepted for recorded NMOCD
Date: 6-18-2020	DS 8-11-2020
Phone: 575-492-1236	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM