

OCD - REC'D 7/24/2020

District I
1621 N. French Dr., Hobbs, NM 88240
Phone: (575) 397-4181 Fax: (575) 397-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name BXP Operating, LLC	API Number 30-015-10906
Property Name North Benson Queen Unit	Well No. 42

UL - Lot F	Section 32	Township 18S	Range 30E	Feet from 1980	NS Line N	Feet from 1980	E/W Line W	County EDDY
---------------	---------------	-----------------	--------------	-------------------	--------------	-------------------	---------------	----------------

Well Status		DATE 6-18-2020	
YES	NO	YES	NO
TA'D WELL	SHUT-IN	INJECTOR	PRODUCER
YES	NO	NO	YES
SWD	OIL	GAS	

OBSERVED DATA

	(A) Surface	(B) Intern (1)	(C) Intern (2)	(D) Prod Csg	(E) Tubing
Pressure	0			0	560
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	C02
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION
Printed name: M.Y. Merchant	Entered into RBDMS
Title: Production Supervisor	Re-test
E-mail Address: mymerch@penrocoil.com	Accepted for record NMOCD
Date: 6-18-2020	DS 8-7-2020
Phone: 575-492-1236	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM