		REC'D NMOCD
Submit 1 Copy To Appropriate District Office	State of New Mexico	11/09/2020 Form C-103
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-015-40835
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	STATE X FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	,	o. State on te das Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		PARKWAY WEST SWD
PROPOSALS.)		8. Well Number 1
1. Type of Well: Oil Well Gas Well Other SWD 2. Name of Operator Devon Energy Production Company, L.P.		9. OGRID Number 6137
3. Address of Operator 333 W. Sheridan Ave Oklahoma City, OK 73102		10. Pool name or Wildcat
4. Well Location		SWD; Silurian-Ordovician
_	1255 feet from the NORTH line and	feet from the WEST line
Section 27	Township 19S Range 29E	NMPM County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3341.4		
12 Check Ar	opropriate Box to Indicate Nature of Notice	re Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING REMEDIAL WORK ARANDON REMEDIAL WORK ARANDON REMEDIAL WORK ARANDON REMEDIAL WORK ARANDON REMEDIAL WORK REMEDIAL WORK REMEDIAL WORK ARANDON REMEDIAL WORK REMED		
TEMPORARILY ABANDON		
DOWNHOLE COMMINGLE	WIGHT EL GOIVILE	
CLOSED-LOOP SYSTEM		_
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
Subsequent Report for Repair		
Devon Energy Production Co., L.P. respectfully reports actual repair operations for the Parkway West SWD 1. Please see below for dated procedure and see attached for MIT.		
10/6-7/20		
• Remove old 4-1/2" poly-lined injection tubing 10/8-9/20		
 Perform preliminary pressure test on casing and permanent packer with test seal assembly and 2-7/8" workstring 10/10/20 		
 Install new seal assembly, new 4-1/2" fiberglass-lined injection tubing, and new tubing hanger Seal into the existing 7" permanent packer and perform preliminary pressure test on annulus 		
10/12/20 • Perform chart-recorded MIT		
10/13/20 • Perform acid stimulation		
r errorm acid stillidiation		
Spud Date: 7/28/2013	Rig Release Date: 9/21/20	13
Please see attached detailed procedur	re and current & proposed wellbore diagram	
I hereby certify that the information ab	ove is true and complete to the best of my knowle	edge and helief
Thereby certify that the information at	ove is true and complete to the best of my known	eage and benefi.
SIGNATURE Regulatory Analyst TITLE Regulatory Analyst		DATE 11/9/2020
Type or print name Rebecca Deal For State Use Only	E-mail address: rebecca.deal@	7 dvn.com PHONE: 405-228-8429
roi state use Omy	Commissions	Llicar
APPROVED BY: Dand molt TITLE Compliance officer DATE 11-20-2020		
Conditions of Approval (if any):		

