

District 2-Artesia Field Office  
811 S. 1<sup>st</sup> Street  
Artesia, NM 88210  
(Office) 575-748-1283  
(Fax) 575-748-9720  
Submit 1 Copy

State of New Mexico  
EMNRD-OIL CONSERVATION DIVISION

## BRADENHEAD TEST REPORT

Operator Name Trinity Environmental SWD 1, LLC		30 API Number 30-015-32122
Property Name OXY T-BONE FEDERAL		Well No. # 1

## 7. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
C	33	18S	31E	660	N	1980	W	EDDY

## Well Status

TA'D Well	SHUT-IN	INJECTOR	PRODUCER	DATE
YES NO	YES NO	INJ <b>SWD</b>	OIL GAS	11-4-2020

## OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure	0	N/A	N/A	0	1200PIS SHUT IN
Flow Characteristics					
Puff	Y / <b>N</b>	Y / N	Y / N	Y / <b>N</b>	CO2 _____
Steady Flow	Y / <b>N</b>	Y / N	Y / N	Y / <b>N</b>	WTR <b>X</b> _____
Surges	Y / <b>N</b>	Y / N	Y / N	Y / <b>N</b>	GAS _____
Down to nothing	Y / <b>N</b>	Y / N	Y / N	Y / <b>N</b>	If applicable type
Gas or Oil	Y / <b>N</b>	Y / N	Y / N	Y / <b>N</b>	fluid injected for
Water	Y / <b>N</b>	Y / N	Y / N	Y / <b>N</b>	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.  
NO PRESSURE ON CASING.

Accepted for record test not witnessed  
NMOCD DS 12-1-2020

Signature: <i>Kevin W. Rogers</i>	OIL CONSERVATION DIVISION
Print name: Kevin W. Rogers	Recorded online:
Title: Operations Manager	Re-test:
E-mail Address: kevin.rogers@trinityenv.com	Phone #: 575-200-7896
Date: 11-5-2020	Witness: