

District II - Artesia811 S. 1st Street, Artesia, NM 88210

Phone: (575) 748-1283 - Fax: (575) 748-9720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name OXY	³ API Number 30-015-42797
Property Name Cedar Canyon 15 SWD 1	Well No.

⁷ Surface Location

UL - Lot	Section 15	Township 24S	Range 29E	Feet from 2500	N ☒ S ☐ Line	Feet From 1400	R/W Line	County Eddy
----------	----------------------	------------------------	---------------------	--------------------------	---	--------------------------	----------	-----------------------

Well Status

TA'D Well	SHUT-IN	INJECTOR	PRODUCER	DATE
YES ☐ NO ☒	YES ☐ NO ☒	INJ ☐ SWD ☒	OIL ☐ GAS ☐	10-19-20

OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure	0			0	802
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO ₂ _____
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR _____
Surges	Y/N	Y/N	Y/N	Y/N	GAS _____
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

A - Puff Gas Down to Nothing
D - Puff Gas Down to Nothing

Denied in complete information
NMOCD DS 12-1-2020

Signature: DS	OIL CONSERVATION DIVISION
Printed name: DS	Entered _____
Title: _____	Re-test _____
E-mail Address DS	
Date: 10-19-20	Phone: DS
Witness: Ray Star	