

District II - Artesia811 S. 1st Street, Artesia, NM 88210

Phone: (575) 748-1283 - Fax: (575) 748-9720

Rec'd 12/03/2020 - NMOCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name oxy	API Number 30-015-25640
Property Name Calmon #	Well No. 5

2. Surface Location

UL - Lot G	Section 35	Township 23S	Range 31E	Feet from 1980	DS Line 1980	Feet From 1980	BW Line 1980	County Eddy
----------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	-----------------------

Well Status

TA'D Well	SHUT-IN	INJECTOR	PRODUCER	DATE
YES NO	YES NO	INJ SWD	OIL GAS	10-12-20

OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure	0			0	775
Flow Characteristics					
Pull	Y/ N	Y/ N	Y/ N	Y/ N	CO2 _____
Steady Flow	Y/ N	Y/ N	Y/ N	Y/ N	WTR _____
Surges	Y/ N	Y/ N	Y/ N	Y/ N	GAS _____
Down to nothing	Y/ N	Y/ N	Y/ N	Y/ N	If applicable type
Gas or Oil	Y/ N	Y/ N	Y/ N	Y/ N	fluid injected for
Water	Y/ N	Y/ N	Y/ N	Y/ N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

A - nothing
D - nothing

Accepted for record test not witnessed
NMOCD DS 12-4-2020

Signature: _____		OIL CONSERVATION DIVISION	
Printed name: Reggie House		Entered _____	
Title: Production Tech II		Re-test _____	
E-mail Address: reggie-house@oxy.com			
Date: 10-12-20	Phone: 575-942-0363		
Signature: Reggie House	Witness: Reggie House		