

District II - Artesia
 811 S. 1st Street, Artesia, NM 88210
 Phone: (575) 748-1283 - Fax: (575) 748-9720

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name DX4	API Number 30-015-26742
Property Name Federal 12-M	Well No. # 001

2. Surface Location

U/L - Lot M	Section 12	Township 22S	Range 31E	Feet from 660	N/S Line South	Feet From 660	E/W Line West	County Eddy
-----------------------	----------------------	------------------------	---------------------	-------------------------	--------------------------	-------------------------	-------------------------	-----------------------

Well Status

TA'D Well YES NO	SHUT-IN YES NO	INJECTOR INJ SWD	PRODUCER OIL GAS	DATE 11-3-2020
---------------------	--------------------------	----------------------------	---------------------	--------------------------

OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure	0	0		0	0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO ₂ _____
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR _____
Surges	Y/N	Y/N	Y/N	Y/N	GAS _____
Down to nothing	Y/N	Y/N	Y/N	Y/N	If applicable type
Gas or Oil	Y/N	Y/N	Y/N	Y/N	fluid injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFOR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

MIT
A - Puff Gas
B - nothing
D - nothing

Accepted for record test not witnessed
 NMOCD DS 12-4-2020

Signature:	OIL CONSERVATION DIVISION
Printed name: Reggie House	Entered _____
Title: Production Tech II	Re-test _____
E-mail Address: reggie_house @ dx4 . com	
Date: 11-3-2020	Phone: 575-942-0363
Signature: Reggie House	Witness: Miguel Sanchez