

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6176 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of	Test _	5-2	6-20	21	Operator	Cross Timbers Energy LLC. API #30-039066470000				
Property Name <u>Breech E</u> Well No. <u>109</u> Location: <u>Rio Arriba County</u> Unit <u>M</u> Section <u>03</u> Township <u>26N</u> Range <u>06W</u>										
Well Status(Shut-In or Producing) Initial PSI: Tubing 130 Intermediate NA Casing 130 Bradenhead O										
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH										
Testing	BH Int Csg Int Csg						FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE			
TIME 5 min_	0	N/A	130			Steady Flow_				
10 min_	0	NA	130			Surges	····			
15 min_	0	NA	130			Down to Noth	ing X			<del></del>
20 min_		ļ <u>.</u>				Nothing				
25 min_						Gas	**			_
30 min_						Gas & Water_				<u> </u>
	•	•				Water			<u> </u>	<del></del>
If bradenhead flowed water, check all of the descriptions that apply below:										
CLEAR FRESH SALTY SULFUR BLACK										
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE NA										
REMARKS:										
2 4										
By Witness										
(Position)										
E-mail address jwaggoner W C+PieldSUCS. Com										