

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-14
Revised August 8, 20

Submit 1 Copy to appropriate District Office
accordance with 19.15.29 NMAC

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company DCP Midstream, LP	Contact Jon Bebbington	
Address 10 Desta Drive, Suite 400 West	Telephone No. 432-620-4207	
Facility Name ?? Line Gas Pipeline	Facility Type Gas Pipeline	
Surface Owner BLM	Mineral Owner	API No.

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County LEA
	7	19S	33E					



Latitude N32.675451 Longitude W-103.696384

NATURE OF RELEASE

Type of Release: Raw Natural Gas	Volume of Release ?? bbl	Volume Recovered ?? bbl
Source of Release ?? Gas Pipeline	Date and Hour of Occurrence 2-10-2015 hour unknown	Date and Hour of Discovery 0930 2-11-2015
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding of OCD (voicemail/email); Randy Pair of BLM (voicemail/email)	
By Whom? Jon Bebbington	Date and Hour 02-11-2015 15:45	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N / A		
Describe Cause of Problem and Remedial Action Taken.* DCP's pipeline ruptured and released approx. MCF of sweet natural gas. More details are forthcoming. DCP is responding to the leak.		
Describe Area Affected and Cleanup Action Taken.*		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Hydrologist	
Printed Name: Jon D. Bebbington	Approved by Environmental Specialist	
Title: Princ. Environmental Engineer	Approval Date: 02/11/2015	Expiration Date: 04/11/2015
E-mail Address: jdbbebbington@dcpmidstream.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 02-11-2015 Phone: 432-620-4207	Site samples required. Delineate and remediate area as per NMOCD guides.	1RP-3531 36785

* Attach Additional Sheets If Necessary

pTO1504256286

nTO1504255907