

INFORMATION ONLY

State of New Mexico

Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company – Siana Oil & Gas Co., LLC	Contact – Tom Ragsdale
Address – 12012 Wickchester Lane	Telephone No. – 713-568-1082
Facility Name - APD Federal Well No. 1	Facility Type – Salt Water Disposal

Surface Owner	Mineral Owner	API No.30-025-28554
---------------	---------------	---------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	10	23S	34E	990	South	1940	East	Lea

Latitude 32.3146172 Longitude -103.4556503

Based on visual evidence volumes not accurate

NATURE OF RELEASE


Type of Release – Produced water	Volume of Release - 2 bbls	Volume Recovered - 2 bbls
Source of Release – Load line connection	Date and Hour of Occurrence 9-29-2015	Date and Hour of Discovery 9-29-2015
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Unknown	
By Whom? Unknown	Date and Hour - Unknown	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	

If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.*
A release of produced water by a vacuum truck was created near the unloading section of the SWD facility. It is probable that a hose connection was leaking during the unloading of produced water into the SWD facility near the load line causing the visible release. As soon as notified, Siana took steps to clean the area and take actions to prevent a similar release.

Describe Area Affected and Cleanup Action Taken.*
The affected loading area (20' X 20') was cleaned and the berms and dikes around this area were reinforced.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Tom M. RAGSDALE	Approved by Environmental Specialist: ///	
Title: President	Approval Date: ///	Expiration Date: ///
E-mail Address: tmragsdale@sianaoil.com	Conditions of Approval: Accepted for record only	Attached <input type="checkbox"/>
Date: 1-11-16 Phone: 713 568 1082		IRP-4185

* Attach Additional Sheets If Necessary

pTO1604852414
nTO1604852253