

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	ARP Production Company, LLC	Contact	Randy L. Madison
Address	309 Silver St., Raton, NM 87740	Telephone No.	Office 575-445-6706 Cell 575-420-1120
Facility Name	VPR E-19 Main Line	Facility Type	Flow Line
Surface Owner	Vermejo Park Ranch	Mineral Owner	APR Production Company, LLC
		API No.	30-007-20309

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	33	32N	19E	1105.1	South	1268.7	East	Colfax

Latitude: N 37.00143 Longitude: W 104.81731

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 20 Barrels	Volume Recovered: 5 Barrels
Source of Release: 8" Produced Water Poly Line	Date and Hour of Occurrence 6/27/17@0900	Date and Hour of Discovery 6/27/17@1200
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Randolph Bayliss	
By Whom? Randy Madison	Date and Hour 6/27/17 @1215	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



8" poly water line was over pressured causing a leak in a fusion collar. The fusion collar was replaced and a short section of line.

Describe Area Affected and Cleanup Action Taken.*

No clean-up was need the water remained in the valve box and a small amount rain down the lease road ditch. The water was of fair quality see attached water analysis of nearest well.

1,836 ppm TDS, 93% NaHCO₃

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Randy L. Madison		Approved by Environmental Specialist: 	
Title: EHS Specialist	Approval Date: 03Jul17	Expiration Date: na	
E-mail Address: rmadison@atlasenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 6/29/17	Phone: 575-445-6706	none	

* Attach Additional Sheets If Necessary

nRAB1718437524

4RP-19