

## BLACK ROCK CRUDE OIL SERVICES LLC

U.S. DOT#: 1462216 Address: 16 ROAD 2690 AZTEC, NM 87410 Number of Vehicles: 5 Number of Drivers: 5 Number of Inspections: 2

### Safety Rating & OOS

#### Rates

(As of 01/08/2020 updated daily from <u>SAFER</u>)

Not Rated

### **Out of Service Rates**

Туре	00S %	National Avg %
Vehicle	50.0	20.7
Driver	50.0	5.5
Hazmat	0.0	4.5

### Licensing and Insurance

(As of 01/08/2020 updated hourly from <u>L&I</u>)

Active For-Hire Authority							
Туре	Yes/N	Yes/No MC#/MX#					
Property	Yes	MC-					
		907022					
Passenger	No						
Household Goods	No						
Broker	No						

Based on a 24-month record ending December 27, 2019

### BASIC Status (Public Property Carrier View) ?

Behavior Analysis & Safety Improvement Categories (BASICs)



# **On-Road Performance**

() Measure	NOT PUBLIC	() Measure	5 Measure	0 Measure	NOT PUBLIC	1.50 Measure
On-Road Perfor	mance Detail					
Driver Inspections with Unsafe Driving Violations: 0		Driver Inspections: 2	Vehicle Inspections: 2	Driver Inspections: 2		Driver Inspections: 2
		with HOS Compliance	with Vehicle Maint.	with Drugs/Alcohol		with Driver Fitness
Safety Event	NOT	Violations: 0	Violations: 1	Violations: 0	NOT	Violations: 1
<b>Group:</b> No Safety Event Grouping	PUBLIC	Safety Event Group: No Safety	Safety Event Group: No Safety	Safety Event Group: No Safety	PUBLIC	Safety Event Group: No Safety
Avg. PU × UF: 7		Event Grouping	. ,	Event Grouping		Event Grouping

Segment: Straight Carrier

## **Investigation Results**

Safety Measurement System - Complete SMS Profile (U.S. DOT# 1462216)

No Acute/Critical	
Violations	
Discovered	

No Acute/Critical Violations Discovered

No Acute/Critical No Acute/Critical Violations Discovered

NOT PUBLIC

No Acute/Critical Violations Discovered

Select a BASIC icon above to get details, or view your Complete SMS Profile.

N/A

# **Summary of Activities**

The summary includes information on the 5 most recent investigations and 24 months of inspections and crash history.

Most Recent Investigation: Total Inspections: 2 Total Inspections without Violations used in SMS: 0 Total Inspections with Violations used in SMS: 2 Total Crashes\*: 0

\*Crashes listed represent a motor carrier's involvement in reportable crashes, regardless of the carrier's or driver's role in the crash. Continue for details.

#### USE OF SMS DATA/INFORMATION

#### FAST Act of 2015:

Readers should not draw conclusions about a carrier's overall safety condition simply based on the data displayed in this system. Unless a motor carrier has received an UNSATISFACTORY safety rating under part 385 of title 49, Code of Federal Regulations, or has otherwise been ordered to discontinue operations by the Federal Motor Carrier Safety Administration, it is authorized to operate on the Nation's roadways.

#### Safety Measurement System:

The data in the Safety Measurement System (SMS) is performance data used by the Agency and Enforcement Community. A 🕰 symbol, based on that data, indicates that FMCSA may prioritize a motor carrier for further monitoring.

The 🕰 symbol is not intended to imply any federal safety rating of the carrier pursuant to 49 USC 31144. Readers should not draw conclusions about a carrier's overall safety condition simply based on the data displayed in this system. Unless a motor carrier in the SMS has received an UNSATISFACTORY safety rating pursuant to 49 CFR Part 385, or has otherwise been ordered to discontinue operations by the FMCSA, it is authorized to operate on the nation's roadways.

Motor carrier safety ratings are available at http://safer.fmcsa.dot.gov and motor carrier licensing and insurance status are available at http://lipublic.fmcsa.dot.gov/.

# **Carrier Registration**

Violations

Discovered

Subject to General Threshold

## **Enforcement Cases**

(Six years as of 01/08/2020 updated monthly from FMCSA)

No penalties found