

# BIGHORN TRANSPORT

# SERVICES LLC

U.S. DOT#: 3333558 Address: 1412 W BERRY DR HOBBS, NM 88240 Number of Vehicles: 5 Number of Drivers: 6 Number of Inspections: 0

## Safety Rating & OOS

#### Rates

(As of 03/08/2020 updated daily from <u>SAFER</u>)

Not Rated

### **Out of Service Rates**

Туре	00S %	National Avg %	
Vehicle		20.7	
Driver		5.5	
Hazmat		4.5	

### Licensing and Insurance

(As of 03/08/2020 updated hourly from <u>L&I</u>)

Active For-Hire Authority							
Туре	Yes/No MC#/MX#						
Property	Yes	MC-					
		1062757					
Passenger	No						
Household Goods	No						
Broker	No						

#### BASIC Status (Public Property Carrier View) ?

Behavior Analysis & Safety Improvement Categories (BASICs)





# **On-Road Performance**

0 Measure	NOT PUBLIC	() Measure	() Measure	0 Measure	NOT PUBLIC	0 Measure
On-Road Perfor	rmance Detail	l				
Driver Inspections with Unsafe Driving		Driver Inspections: 0 with HOS	Vehicle Inspections: 0 with Vehicle	Driver Inspections: 0 with		Driver Inspections: 0 with Driver
Violations: 0 Safety Event	NOT PUBLIC	Compliance Violations: 0	Maint. Violations: 0	Drugs/Alcohol Violations: 0	NOT	Fitness Violations: 0
<b>Group:</b> No Safety Event Grouping		Safety Event Group: No Safety	Safety Event Group: No Safety	Safety Event Group: No Safety	NOT PUBLIC	Safety Event Group: No Safety
Avg. PU × UF: 5		Event Grouping	Event Grouping	Event Grouping		Event Grouping

Segment: Combination Carrier

## **Investigation Results**

No Acute/Critical
Violations
Discovered

N/A D

No Acute/Critical N Violations V Discovered E

No Acute/Critical No Acute/Critical Violations Violations Discovered Discovered

NOT PUBLIC No Acute/Critical Violations Discovered

Select a BASIC icon above to get details, or view your Complete SMS Profile.

# **Summary of Activities**

The summary includes information on the 5 most recent investigations and 24 months of inspections and crash history.

Most Recent Investigation: Total Inspections: 0 Total Inspections without Violations used in SMS: 0 Total Inspections with Violations used in SMS: 0

Total Crashes\*:0

\*Crashes listed represent a motor carrier's involvement in <u>reportable</u> <u>crashes</u>, regardless of the carrier's or driver's role in the crash. <u>Continue</u> <u>for details</u>.

# **Carrier Registration**

Subject to General Threshold

## **Enforcement Cases**

(Six years as of 03/08/2020 updated monthly from <u>FMCSA</u>)

No penalties found

#### USE OF SMS DATA/INFORMATION

#### FAST Act of 2015:

Readers should not draw conclusions about a carrier's overall safety condition simply based on the data displayed in this system. Unless a motor carrier has received an UNSATISFACTORY safety rating under part 385 of title 49, Code of Federal Regulations, or has otherwise been ordered to discontinue operations by the Federal Motor Carrier Safety Administration, it is authorized to operate on the Nation's roadways.

#### Safety Measurement System:

The data in the Safety Measurement System (SMS) is performance data used by the Agency and Enforcement Community. A 🕰 symbol, based on that data, indicates that FMCSA may prioritize a motor carrier for further monitoring.

The A symbol is not intended to imply any federal safety rating of the carrier pursuant to 49 USC 31144. Readers should not draw conclusions about a carrier's overall safety condition simply based on the data displayed in this system. Unless a motor carrier in the SMS has received an UNSATISFACTORY safety rating pursuant to 49 CFR Part 385, or has otherwise been ordered to discontinue operations by the FMCSA, it is authorized to operate on the nation's roadways.

Motor carrier safety ratings are available at <u>http://safer.fmcsa.dot.gov</u> and motor carrier licensing and insurance status are available at <u>http://li-public.fmcsa.dot.gov/</u>.