

PRIME PARTNERS INC

DBA: PRIME ENERGY

U.S. DOT#: 3288206

Address: 3901 N CENTRAL DR #E108

HOBBS, NM 88240 Number of Vehicles: 6 Number of Drivers: 6 Number of Inspections: 6

Safety Rating & OOS Rates

(As of 07/15/2020 updated daily from SAFER)

Not Rated

Out of Service Rates

Type	00S %	National Avg %
Vehicle	80.0	20.7
Driver	0.0	5.5
Hazmat		4.5

Licensing and Insurance

(As of 07/15/2020 updated hourly from L&I)

Active For-Hire Authority

Туре	Yes/N	o MC#/MX#
Property	Yes	MC- 1040816
Passenger	No	20.0020
Household Goods	No	
Broker	No	

BASIC Status (Public Property Carrier View) ?

Behavior Analysis & Safety Improvement Categories (BASICs)



Unsafe Driving











Based on a 24-month record ending June 26, 2020



Not Public

Crash Indicator

Hours-of-Service Compliance

Vehicle Maintenance

Controlled Substances and Alcohol

Not Public Hazardous Materials Compliance

Driver Fitness

On-Road Performance

3 Measure	NOT	() Measure	17.22 Measure	0 Measure	NOT	0 Measure
	PUBLIC				PUBLIC	

On-Road Performance Detail

Driver Inspections with Unsafe Driving Violations: 1	
Safety Event Group: No Safety Event Grouping	

Avg. PU × UF: 4 Segment: Combination

Carrier

NOT **PUBLIC** Driver **Inspections:** 6 with HOS Compliance Violations: 0 Safety Event **Group:** 3-10

Vehicle Inspections: 4 with Vehicle Maint. Violations: 4 Safety Event relevant driver inspections

Driver **Inspections:** 6 with Drugs/Alcohol Violations: 0 Safety Event **Group:** No Safety **Group:** No Safety **Event Grouping Event Grouping**

NOT **PUBLIC**

Driver **Inspections:** 6 with Driver **Fitness** Violations: 0 Safety Event Group: 5-10 relevant driver inspections

Investigation Results

No Acute/Critical Violations Discovered

N/A

No Acute/Critical Violations Discovered

No Acute/Critical Violations Discovered No Acute/Critical Violations Discovered

NOT PUBLIC No Acute/Critical Violations Discovered

Select a BASIC icon above to get details, or view your Complete SMS Profile.

Summary of Activities

The summary includes information on the 5 most recent investigations and 24 months of inspections and crash history.

Most Recent Investigation: Total Inspections: 6

> Total Inspections without Violations used in SMS: 1 Total Inspections with Violations used in SMS: 5

Total Crashes*: 0

*Crashes listed represent a motor carrier's involvement in reportable crashes, regardless of the carrier's or driver's role in the crash. Continue for details.

Carrier Registration

Subject to General Threshold

Enforcement Cases

(Six years as of 07/15/2020 updated monthly from <u>FMCSA</u>)

No penalties found

USE OF SMS DATA/INFORMATION

FAST Act of 2015:

Readers should not draw conclusions about a carrier's overall safety condition simply based on the data displayed in this system. Unless a motor carrier has received an UNSATISFACTORY safety rating under part 385 of title 49, Code of Federal Regulations, or has otherwise been ordered to discontinue operations by the Federal Motor Carrier Safety Administration, it is authorized to operate on the Nation's roadways.

Safety Measurement System:

The data in the Safety Measurement System (SMS) is performance data used by the Agency and Enforcement Community. A symbol, based on that data, indicates that FMCSA may prioritize a motor carrier for further monitoring.

The symbol is not intended to imply any federal safety rating of the carrier pursuant to 49 USC 31144. Readers should not draw conclusions about a carrier's overall safety condition simply based on the data displayed in this system. Unless a motor carrier in the SMS has received an UNSATISFACTORY safety rating pursuant to 49 CFR Part 385, or has otherwise been ordered to discontinue operations by the FMCSA, it is authorized to operate on the nation's roadways.

Motor carrier safety ratings are available at http://safer.fmcsa.dot.gov and motor carrier licensing and insurance status are available at http://li-public.fmcsa.dot.gov/.