

1R - 423-03

REPORTS

DATE:

10/25/2002

1R0423-03

FINAL REPORT

**RICE OPERATING COMPANY
JUNCTION BOX FINAL REPORT**

BOX LOCATION

SWD SYSTEM	JUNCTION	UNIT	SECTION	TOWNSHIP	RANGE	COUNTY	BOX DIMENSIONS - FEET		
Justis	B-26	B	26	25 S	37 E	Lea	Length 7	Width 5	Depth 7

LAND TYPE: BLM _____ STATE _____ FEE LANDOWNER _____ G. Willis _____ OTHER _____

Depth to Groundwater _____ 75 _____ feet NMOCD SITE ASSESSMENT RANKING SCORE: _____ 10 _____

Date Started _____ 7/1/2002 _____ Date Completed _____ 9/30/2002 _____ OCD Witness _____ No _____

Soil Excavated _____ 550 _____ cubic yards Excavation Length _____ 20 _____ Width _____ 35 _____ Depth _____ 22 _____ feet

Soil Disposed _____ 0 _____ cubic yards Offsite Facility _____ n/a _____ Location _____ n/a _____

FINAL ANALYTICAL RESULTS: Sample Date _____ 9/27/2002 _____ Sample Depth _____ 22 ft _____

Procure 5-point composite sample of bottom and 4-point composite sample of sidewalls. TPH, BTEX and Chloride laboratory test results completed by using an approved lab and testing procedures pursuant to NMOCD guidelines.

Sample Location	Benzene mg/kg	Toluene mg/kg	Ethyl Benzene mg/kg	Total Xylenes mg/kg	GRO mg/kg	DRO mg/kg	Chlorides mg/kg
SIDEWALLS	<0.025	<0.025	<0.025	<0.025	<10.0	<10.0	153
BOTTOM	<0.025	<0.025	<0.025	<0.045	<10.0	44.8	319
REMEDIATED	<0.025	<0.025	<0.025	<0.025	<10.0	38.6	674

General Description of Remedial Action: In July, vertical delineation revealed TPH

impact below the box down to 22' where the concentration was 194 ppm. A hard sandstone layer was encountered just below 22' BGS. Chlorides diminished vertically at 8'. TPH was negligible in the lateral directions of 20' west, 17' east, 10' south, and 10' north. The chloride boundary was found at 20' west, 25' east, 10' south, and 10' north where concentrations were below 1000 ppm and a vertical decline was also found. A 20' x 35' x 22' excavation under the location was completed in September. A bottom composite sample at 22' BGS revealed 44.8 ppm TPH and 319 ppm chlorides. The wall composite yielded <10 ppm TPH and 153 ppm chlorides. The removed soil was landfarmed on location and backfilled into the excavation. The remediated soil tested 38.6 ppm TPH and 674 ppm chlorides, these concentrations should not threaten groundwater. A water-tight junction box has been built at this location.

cc: lab results

CHLORIDE FIELD TESTS

LOCATION	DEPTH	ppm
Vertical	6	3120
	12	736
	16	60
10' W	6	2760
	16	130
25' E	6	620
	16	550
10' N	6	720
	16	350
10' S	16	540

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

DATE _____ 10-25-02 _____ PRINTED NAME _____ Kristin Farris _____

SIGNATURE _____ Kristin Farris _____ TITLE _____ Environmental Projects Scientist _____

Justis B-26 jet. with vent



Old box before NORM removal



NORM Removal



New Plumbing

Justis B-26 jct. with vent



↓ Environmental Impact Excavation ↑



New Junction Box

B. 26
Remediated

ANALYTICAL REPORT

Prepared for:

LOGAN ANDERSON
RE ENVIRONMENTAL
P.O. BOX 13418
ODESSA, TX 79768

Project: RICE

PO#:

Order#: G0204682

Report Date: 10/04/2002

Certificates

US EPA Laboratory Code TX00158

ENVIRONMENTAL LAB OF TEXAS

SAMPLE WORK LIST

RE ENVIRONMENTAL
P.O. BOX 13418
ODESSA, TX 79768
366-0804

Order#: G0204682
Project:
Project Name: RICE
Location: B-26

The samples listed below were submitted to Environmental Lab of Texas and were received under chain of custody. Environmental Lab of Texas makes no representation or certification as to the method of sample collection, sample identification, or transportation/handling procedures used prior to the receipt of samples by Environmental Lab of Texas, unless otherwise noted.

<u>Lab ID:</u>	<u>Sample :</u>	<u>Matrix:</u>	<u>Date / Time</u> <u>Collected</u>	<u>Date / Time</u> <u>Received</u>	<u>Container</u>	<u>Preservative</u>
0204682-01	REMEDIATED COMP. PILE	SOIL	9/30/02 14:00	10/1/02 9:40	4 oz Glass	ICE
	<u>Lab Testing:</u>	Rejected: No		Temp: 18.5 C		
	8015M					
	8021B/5030 BTEX					
	Chloride					

ENVIRONMENTAL LAB OF TEXAS

ANALYTICAL REPORT

LOGAN ANDERSON
RE ENVIRONMENTAL
P.O. BOX 13418
ODESSA, TX 79768

Order#: G0204682
Project:
Project Name: RICE
Location: B-26

Lab ID: 0204682-01
Sample ID: REMEDIATED COMP. PILE

8015M

Method	Date	Date	Sample	Dilution		
<u>Blank</u>	<u>Prepared</u>	<u>Analyzed</u>	<u>Amount</u>	<u>Factor</u>	<u>Analyst</u>	<u>Method</u>
		10/2/02	1	1	RKT	8015M

Parameter	Result mg/kg	RL
GRO, C6-C12	<10.0	10.0
DRO, >C12-C35	38.6	10.0
TOTAL, C6-C35	38.6	10.0

8021B/5030 BTEX

Method	Date	Date	Sample	Dilution		
<u>Blank</u>	<u>Prepared</u>	<u>Analyzed</u>	<u>Amount</u>	<u>Factor</u>	<u>Analyst</u>	<u>Method</u>
0003280-02		10/2/02 10:40	1	25	CK	8021B

Parameter	Result mg/kg	RL
Benzene	<0.025	0.025
Ethylbenzene	<0.025	0.025
Toluene	<0.025	0.025
p/m-Xylene	<0.025	0.025
o-Xylene	<0.025	0.025

Surrogates	% Recovered	QC Limits (%)	
aaa-Toluene	88%	80	120
Bromofluorobenzene	89%	80	120

Approval: Jeanne McMurrey 10-07-02
Raland K. Tuttle, Lab Director, QA Officer Date
Celey D. Keene, Org. Tech. Director
Jeanne McMurrey, Inorg. Tech. Director
Sandra Biezugbe, Lab Tech.
Sara Molina, Lab Tech.

DL = Diluted out N/A = Not Applicable RL = Reporting Limit

Page 1 of 1

ENVIRONMENTAL LAB OF TEXAS

ANALYTICAL REPORT

LOGAN ANDERSON
RE ENVIRONMENTAL
P.O. BOX 13418
ODESSA, TX 79768

Order#: G0204682
Project:
Project Name: RICE
Location: B-26

Lab ID: 0204682-01
Sample ID: REMEDIATED COMP. PILE

Test Parameters

<u>Parameter</u>	<u>Result</u>	<u>Units</u>	<u>Dilution Factor</u>	<u>RL</u>	<u>Method</u>	<u>Date Analyzed</u>	<u>Analyst</u>
Chloride	674	mg/kg	1	20	9253	10/4/02	SB

Approval: Jeanne McMurrey 10-07-02
Raland K. Tuttle, Lab Director, QA Officer Date
Celey D. Keene, Org. Tech. Director
Jeanne McMurrey, Inorg. Tech. Director
Sandra Biezugbe, Lab Tech.
Sara Molina, Lab Tech.

ENVIRONMENTAL LAB OF TEXAS

QUALITY CONTROL REPORT

8015M

Order#: G0204682

BLANK	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
TOTAL, C6-C35-mg/kg		0003275-02			<10.0		
MS	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
TOTAL, C6-C35-mg/kg		0204680-02	0	952	1063	111.7%	
MSD	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
TOTAL, C6-C35-mg/kg		0204680-02	0	952	1135	119.2%	6.6%
SRM	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
TOTAL, C6-C35-mg/kg		0003275-05		1000	880	88.0%	

ENVIRONMENTAL LAB OF TEXAS

QUALITY CONTROL REPORT

8021B/5030 BTEX

Order#: G0204682

BLANK	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-mg/kg		0003280-02			<0.025		
Ethylbenzene-mg/kg		0003280-02			<0.025		
Toluene-mg/kg		0003280-02			<0.025		
p/m-Xylene-mg/kg		0003280-02			<0.025		
o-Xylene-mg/kg		0003280-02			<0.025		
MS	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-mg/kg		0204636-01	0	0.1	0.096	96.%	
Ethylbenzene-mg/kg		0204636-01	0	0.1	0.100	100.%	
Toluene-mg/kg		0204636-01	0	0.1	0.100	100.%	
p/m-Xylene-mg/kg		0204636-01	0	0.2	0.212	106.%	
o-Xylene-mg/kg		0204636-01	0	0.1	0.099	99.%	
MSD	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-mg/kg		0204636-01	0	0.1	0.094	94.%	2.1%
Ethylbenzene-mg/kg		0204636-01	0	0.1	0.102	102.%	2.%
Toluene-mg/kg		0204636-01	0	0.1	0.098	98.%	2.%
p/m-Xylene-mg/kg		0204636-01	0	0.2	0.219	109.5%	3.2%
o-Xylene-mg/kg		0204636-01	0	0.1	0.101	101.%	2.%
SRM	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-mg/kg		0003280-05		0.1	0.090	90.%	
Ethylbenzene-mg/kg		0003280-05		0.1	0.094	94.%	
Toluene-mg/kg		0003280-05		0.1	0.094	94.%	
p/m-Xylene-mg/kg		0003280-05		0.2	0.201	100.5%	
o-Xylene-mg/kg		0003280-05		0.1	0.094	94.%	

ENVIRONMENTAL LAB OF TEXAS

QUALITY CONTROL REPORT

Test Parameters

Order#: G0204682

BLANK	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg		0003347-01			<20.0		
MS	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg		0204661-01	354	1000	1350	99.6%	
MSD	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg		0204661-01	354	1000	1330	97.6%	1.5%
SRM	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg		0003347-04		5000	4960	99.2%	

Wessa, Texas 79763

CHAIN OF CUSTODY RECORD AND ANALYSIS REQUEST

Project Manager:

Logan Anderson

RE

Company Name

Company Address:

City/State/Zip:

Telephone No:

Sampler Signature:

Index

[illegible]

B-26

ANALYTICAL REPORT

Prepared for:

LOGAN ANDERSON
RE ENVIRONMENTAL
P.O. BOX 13418
ODESSA, TX 79768

Project: RICE

PO#:

Order#: G0204680

Report Date: 10/04/2002

Certificates

US EPA Laboratory Code TX00158

ENVIRONMENTAL LAB OF TEXAS

SAMPLE WORK LIST

RE ENVIRONMENTAL
P.O. BOX 13418
ODESSA, TX 79768
366-0804

Order#: G0204680
Project:
Project Name: RICE
Location: B-26

The samples listed below were submitted to Environmental Lab of Texas and were received under chain of custody. Environmental Lab of Texas makes no representation or certification as to the method of sample collection, sample identification, or transportation/handling procedures used prior to the receipt of samples by Environmental Lab of Texas, unless otherwise noted.

<u>Lab ID:</u>	<u>Sample :</u>	<u>Matrix:</u>	<u>Date / Time</u>	<u>Date / Time</u>	<u>Container</u>	<u>Preservative</u>
			<u>Collected</u>	<u>Received</u>		
0204680-01	5 PT. BOTTOM COMP.	SOIL	9/27/02	10/1/02	4 oz Glass	ICE
	@ 22 FT.		11:00	9:40		
	<u>Lab Testing:</u>	Rejected: No		Temp: 18.5 C		
	8015M					
0204680-02	8021B/5030 BTEX				4 oz Glass	ICE
	Chloride					
	4 PT. WALL COMP. @	SOIL	9/27/02	10/1/02		
	21 FT.		11:00	9:40		
0204680-03	<u>Lab Testing:</u>	Rejected: No		Temp: 18.5 C	4 oz Glass	ICE
	8015M					
	8021B/5030 BTEX					
	Chloride					
0204680-03	VERTICAL @ 22 FT.	SOIL	9/27/02	10/1/02	4 oz Glass	ICE
			11:00	9:40		
	<u>Lab Testing:</u>	Rejected: No		Temp: 18.5 C		
	8015M					
0204680-03	8021B/5030 BTEX				4 oz Glass	ICE
	Chloride					

ENVIRONMENTAL LAB OF TEXAS

ANALYTICAL REPORT

LOGAN ANDERSON
RE ENVIRONMENTAL
P.O. BOX 13418
ODESSA, TX 79768

Order#: G0204680
Project:
Project Name: RICE
Location: B-26

Lab ID: 0204680-01
Sample ID: 5 PT. BOTTOM COMP. @ 22 FT.

8015M

<u>Method</u>	<u>Date</u>	<u>Date</u>	<u>Sample</u>	<u>Dilution</u>	<u>Analyst</u>	<u>Method</u>
<u>Blank</u>	<u>Prepared</u>	<u>Analyzed</u>	<u>Amount</u>	<u>Factor</u>		
		10/2/02	1	1	RKT	8015M

Parameter	Result mg/kg	RL
GRO, C6-C12	<10.0	10.0
DRO, >C12-C35	44.8	10.0
TOTAL, C6-C35	44.8	10.0

8021B/5030 BTEX

<u>Method</u>	<u>Date</u>	<u>Date</u>	<u>Sample</u>	<u>Dilution</u>	<u>Analyst</u>	<u>Method</u>
<u>Blank</u>	<u>Prepared</u>	<u>Analyzed</u>	<u>Amount</u>	<u>Factor</u>		
0003280-02		10/1/02 23:10	1	25	CK	8021B

Parameter	Result mg/kg	RL
Benzene	<0.025	0.025
Ethylbenzene	<0.025	0.025
Toluene	<0.025	0.025
p/m-Xylene	0.032	0.025
o-Xylene	<0.025	0.025

Surrogates	% Recovered	QC Limits (%)	
aaa-Toluene	92%	80	120
Bromofluorobenzene	100%	80	120

ENVIRONMENTAL LAB OF TEXAS

ANALYTICAL REPORT

LOGAN ANDERSON
RE ENVIRONMENTAL
P.O. BOX 13418
ODESSA, TX 79768

Order#: G0204680
Project:
Project Name: RICE
Location: B-26

Lab ID: 0204680-02
Sample ID: 4 PT. WALL COMP. @ 21 FT.

8015M

Method	Date	Date	Sample	Dilution		
<u>Blank</u>	<u>Prepared</u>	<u>Analyzed</u>	<u>Amount</u>	<u>Factor</u>	<u>Analyst</u>	<u>Method</u>
		10/2/02	1	1	RKT	8015M

Parameter	Result mg/kg	RL
GRO, C6-C12	<10.0	10.0
DRO, >C12-C35	<10.0	10.0
TOTAL, C6-C35	<10.0	10.0

8021B/5030 BTEX

Method	Date	Date	Sample	Dilution		
<u>Blank</u>	<u>Prepared</u>	<u>Analyzed</u>	<u>Amount</u>	<u>Factor</u>	<u>Analyst</u>	<u>Method</u>
0003280-02		10/1/02 23:32	1	25	CK	8021B

Parameter	Result mg/kg	RL
Benzene	<0.025	0.025
Ethylbenzene	<0.025	0.025
Toluene	<0.025	0.025
p/m-Xylene	<0.025	0.025
o-Xylene	<0.025	0.025

Surrogates	% Recovered	QC Limits (%)	
aaa-Toluene	86%	80	120
Bromofluorobenzene	93%	80	120

DL = Diluted out N/A = Not Applicable RL = Reporting Limit

Page 2 of 3

ENVIRONMENTAL LAB OF TEXAS

ANALYTICAL REPORT

LOGAN ANDERSON
RE ENVIRONMENTAL
P.O. BOX 13418
ODESSA, TX 79768

Order#: G0204680
Project:
Project Name: RICE
Location: B-26

Lab ID: 0204680-03
Sample ID: VERTICAL @ 22 FT.

8015M

Method	Date	Date	Sample	Dilution	Analyst	Method
<u>Blank</u>	<u>Prepared</u>	<u>Analyzed</u>	<u>Amount</u>	<u>Factor</u>		
		10/2/02	1	1	RKT	8015M

Parameter	Result mg/kg	RL
GRO, C6-C12	28.5	10.0
DRO, >C12-C35	170	10.0
TOTAL, C6-C35	194	10.0

8021B/5030 BTEX

Method	Date	Date	Sample	Dilution	Analyst	Method
<u>Blank</u>	<u>Prepared</u>	<u>Analyzed</u>	<u>Amount</u>	<u>Factor</u>		
0003280-02		10/1/02 23:54	1	25	CK	8021B

Parameter	Result mg/kg	RL
Benzene	<0.025	0.025
Ethylbenzene	0.038	0.025
Toluene	<0.025	0.025
p/m-Xylene	0.115	0.025
o-Xylene	<0.025	0.025

Surrogates	% Recovered	QC Limits (%)	
aaa-Toluene	86%	80	120
Bromofluorobenzene	95%	80	120

Approval: Jeanne McMurrey 10-08-02
Raland K. Tuttle, Lab Director, QA Officer Date
Celey D. Keene, Org. Tech. Director
Jeanne McMurrey, Inorg. Tech. Director
Sandra Biezugbe, Lab Tech.
Sara Molina, Lab Tech.

DL = Diluted out N/A = Not Applicable RL = Reporting Limit

Page 3 of 3

ENVIRONMENTAL LAB OF TEXAS

ANALYTICAL REPORT

LOGAN ANDERSON
RE ENVIRONMENTAL
P.O. BOX 13418
ODESSA, TX 79768

Order#: G0204680
Project:
Project Name: RICE
Location: B-26

Lab ID: 0204680-01
Sample ID: 5 PT. BOTTOM COMP. @ 22 FT.

Test Parameters

<u>Parameter</u>	<u>Result</u>	<u>Units</u>	<u>Dilution Factor</u>	<u>RL</u>	<u>Method</u>	<u>Date Analyzed</u>	<u>Analyst</u>
Chloride	319	mg/kg	1	20	9253	10/4/02	SB

Lab ID: 0204680-02
Sample ID: 4 PT. WALL COMP. @ 21 FT.

Test Parameters

<u>Parameter</u>	<u>Result</u>	<u>Units</u>	<u>Dilution Factor</u>	<u>RL</u>	<u>Method</u>	<u>Date Analyzed</u>	<u>Analyst</u>
Chloride	153	mg/kg	1	20	9253	10/4/02	SB

Lab ID: 0204680-03
Sample ID: VERTICAL @ 22 FT.

Test Parameters

<u>Parameter</u>	<u>Result</u>	<u>Units</u>	<u>Dilution Factor</u>	<u>RL</u>	<u>Method</u>	<u>Date Analyzed</u>	<u>Analyst</u>
Chloride	188	mg/kg	1	20	9253	10/4/02	SB

Approval: Jeanne McMurrey 10-08-02
Raland K. Tuttle, Lab Director, QA Officer Date
Celey D. Keene, Org. Tech. Director
Jeanne McMurrey, Inorg. Tech. Director
Sandra Biezugbe, Lab Tech.
Sara Molina, Lab Tech.

ENVIRONMENTAL LAB OF TEXAS

QUALITY CONTROL REPORT

8015M

Order#: G0204680

BLANK	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
TOTAL, C6-C35-mg/kg		0003275-02			<10.0		
MS	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
TOTAL, C6-C35-mg/kg		0204680-02	0	952	1063	111.7%	
MSD	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
TOTAL, C6-C35-mg/kg		0204680-02	0	952	1135	119.2%	6.6%
SRM	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
TOTAL, C6-C35-mg/kg		0003275-05		1000	880	88.0%	

ENVIRONMENTAL LAB OF TEXAS

QUALITY CONTROL REPORT

8021B/5030 BTEX

Order#: G0204680

BLANK	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-mg/kg		0003280-02			<0.025		
Ethylbenzene-mg/kg		0003280-02			<0.025		
Toluene-mg/kg		0003280-02			<0.025		
p/m-Xylene-mg/kg		0003280-02			<0.025		
o-Xylene-mg/kg		0003280-02			<0.025		
MS	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-mg/kg		0204636-01	0	0.1	0.096	96.0%	
Ethylbenzene-mg/kg		0204636-01	0	0.1	0.100	100.0%	
Toluene-mg/kg		0204636-01	0	0.1	0.100	100.0%	
p/m-Xylene-mg/kg		0204636-01	0	0.2	0.212	106.0%	
o-Xylene-mg/kg		0204636-01	0	0.1	0.099	99.0%	
MSD	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-mg/kg		0204636-01	0	0.1	0.094	94.0%	2.1%
Ethylbenzene-mg/kg		0204636-01	0	0.1	0.102	102.0%	2.0%
Toluene-mg/kg		0204636-01	0	0.1	0.098	98.0%	2.0%
p/m-Xylene-mg/kg		0204636-01	0	0.2	0.219	109.5%	3.2%
o-Xylene-mg/kg		0204636-01	0	0.1	0.101	101.0%	2.0%
SRM	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Benzene-mg/kg		0003280-05		0.1	0.090	90.0%	
Ethylbenzene-mg/kg		0003280-05		0.1	0.094	94.0%	
Toluene-mg/kg		0003280-05		0.1	0.094	94.0%	
p/m-Xylene-mg/kg		0003280-05		0.2	0.201	100.5%	
o-Xylene-mg/kg		0003280-05		0.1	0.094	94.0%	

ENVIRONMENTAL LAB OF TEXAS

QUALITY CONTROL REPORT

Test Parameters

Order#: G0204680

BLANK	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg		0003347-01			<20.0		
MS	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg		0204661-01	354	1000	1350	99.6%	
MSD	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg		0204661-01	354	1000	1330	97.6%	1.5%
SRM	SOIL	LAB-ID #	Sample Concentr.	Spike Concentr.	QC Test Result	Pct (%) Recovery	RPD
Chloride-mg/kg		0003347-04		5000	4960	99.2%	

12600 West I-20 East
Odessa, Texas 79763

Phone: 915-563-1800
Fax: 915-563-1713

CHAIN OF CUSTODY RECORD AND ANALYSIS REQUEST

Project Manager:

Ogan Anderson

Project Name:

Rice

Company Name

2

Project :-

8-26

Company Address:

City/State/Zip:

Telephone No:

20
21
22
23
24

Sampler Signature:

228

[illegible]

Special Instructions:

Rein. equipped by:

()

10

Received by

1519

5311

Refracted by:

1	100
---	-----

Time

Revised

प्राप्त

Time

Sample Containers intact?
Temperature Upon Receipt
Laboratory Containers

18.50