3**R** - <u>95</u>

GENERAL CORRESPONDENCE

YEAR(S): 1999 - 1996



OIL CONSERVATION DIVISION 2040 South Pacheco Street Santa Fe, New Mexico 87505 (505) 827-7131

September 28, 1999

Ms. Shirley Ebert Conoco, Inc. 10 Desta Dr., Suite 100W Midland, Texas 79705-4500

RE: FINAL SAN JUAN BASIN PIT CLOSURE REPORTS

Dear Ms. Ebert:

The New Mexico Oil Conservation Division (OCD) has reviewed Conoco's August 9, 1999 "CONOCO GROUNDWATER REPORT SUMMARY" which was received by the OCD on September 11, 1999. This document which was submitted on behalf of Conoco by their consultant On Site Technologies, Ltd. requests the status of approval of the corrective actions at a number of pit sites in the San Juan Basin.

A review of the case files on these sites shows there have been recommendations from On Site Technologies to Conoco that Conoco seek closure of the remedial actions at some of the sites. However, the OCD has no record of receiving any closure requests from Conoco. If Conoco wishes to seek closure of the pits at these sites, Conoco will need to submit a completed OCD "Pit Remediation and Closure Report" form for each site. The report should include the results of all soil and ground water remediation actions and information on the current operator of the site.

If you have any questions, please call me at (505) 827-7154.

Sincerely,

William C. Olson Hydrologist Environmental Bureau

xc: Denny Foust, OCD Aztec District Office Larry Trujillo, On Site Technologies, Ltd.



<u>855</u>

1000

August 9, 1999

Mr. Wm. "Bill" Olsen, Hydrologist NMOCD 2040 S. PACHECO ST Santa Fe, NM, 87505

RE: Conoco Groundwater Report Summary

On behalf of Conoco Inc., **On Site Technologies Limited Partnership** requests a status of approval for the corrective actions on the following list of well locations.

LOCATION NAME	LEGAL DESCRIPTION	RECOMMENDATION
RECOMMEND	CONTINUED	Monitoring
Farmington B Com 1	Unit H, S 12, T29N, R12W	WSP-1 still has high BTEX, all other at or below NMWQCC standards, continue monitoring of WSP #1
San Juan 28-7#19	Unit G, S 25, T28N, R7W	Continue monitoring, BTEX levels still above NMWQCC standards
San Juan 28-7#47	Unit A, S 20, T28N, R7W	Continue monitoring, BTEX levels still above NMWQCC standards
Nell-Hall#1	Unit M, S 07, T30N, R11W	Continue to monitor as required in NMCOD letter dated September, 1998
Farmington C Com 1	Unit L, S 15, T29N, R13W	Continue to monitor as required in NMCOD letter dated September, 1998
Farmington B Com 1E	Unit O, S 15, T29N, R13W	Continue to monitor as required in NMCOD letter dated September, 1998
Salmon # 1	Unit P, S 30, T29N, R11W	DG#2 still has high BTEX, Continue monitoring in accordance with NMOCD letter dated September, 1998
RECOMMEND	CLOSURE	
San Juan 28-7#126	Unit M, S 1, T27N, R7W	4 quarters of sampling below NMWQCC standards, recommend closure
San Juan 28-7#219	Unit N, S 20, T28N, R7W	4 quarters of sampling below NMWQCC standards, recommend closure
S&K1	Unit L, S 29, T29N, R11W	4 quarters of sampling below NMWQCC standards recommend closure.
Farmington Com 1	Unit P, S 11, T29N, R13W	Contamination level in MW 1 below OCD action levels for the last four quarters, MW2 and MW3 historically have not had any contamination above NMWQCC standards. Recommend closure of the location.
S&K1E	Unit D, S 29, T29N, R11W	4 quarters of sampling below OCD action levels recommend closure.

Conoco Inc. On Site Technologies, Ltd.



Recommendations listed above were included in the 1997 and 1998 Conoco Annual Ground Water Reports. Please advise *On Site* and Conoco of NMOCD's approval, as we are only scheduling the sites requiring continued monitoring.

If there are any questions or concerns on this matter, feel free to contact me at (505) 325-5667.

Thank you for your time and considerations.

Respectfully submitted,

Larry Trujillo CHMM Senior Environmental Technician On Site Technologies Limited Partnership

CC:

ŝ

Shirley Ebert, SHEAR, Conoco Inc., Farmington Office Neal Goates, Sr. Environmental Specialist, Conoco Inc. STATE OF NEW MEXICO



ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION 2040 S. PACHECO SANTA FE, NEW MEXICO 87505 (505) 827-7131

June 5, 1998

CERTIFIED MAIL RETURN RECEIPT NO, Z-235-437-284

Ms. Shirley Ebert Conoco, Inc. 3315 Bloomfield Hwy. Farmington, New Mexico 87401

RE: GROUND WATER INVESTIGATIONS SAN JUAN BASIN PIT CLOSURES

Dear Ms. Ebert:

The New Mexico Oil Conservation Division (OCD) has completed a review of Conoco, Inc.'s (Conoco) February 4, 1998 "CONOCO'S 1997 ANNUAL GROUNDWATER REPORT" which was received by the OCD on February 27, 1998. This document, which was submitted on behalf of Conoco by their consultant On Site Technologies, Ltd., contains the results of Conoco's investigation, remediation and monitoring at 12 unlined oil and gas production pit sites with resulting ground water contamination.

Upon a review of the above referenced documents, the OCD has the following comments and requirements:

- 1. The data in the reports for the sites listed below show that the complete extent of ground water contamination has not been determined. The OCD requires that Conoco complete the definition of the extent of ground water contamination at these sites pursuant to Conoco's prior approved ground water investigation and remediation plan for the San Juan Basin.
 - Farmington B Com #1
 - Farmington C Com #1
 - Farmington Com #1
 - Nell-Hall #1
 - Salmon #1

- Unit H, Sec. 12, T29N, R12W. Unit L, Sec. 15, T29N, R13W. Unit P, Sec. 11, T29N, R13W. Unit M, Sec. 07, T30N, R11W. Unit P, Sec. 30, T29N, R11W.
- 2. The ground water metals data for the site listed below shows that the concentrations of barium, chromium and lead in ground water are above the New Mexico Water Quality Control Commission (WQCC) ground water standards. The OCD requires that Conoco conduct additional metals sampling at this site
 - Farmington Com #1

Unit P, Sec. 11, T29N, R13W.

Ms. Shirley Ebert June 5, 1998 Page 2

- 3. Some of the report site maps do not show the former locations of the pits, the excavated areas nor the locations of all monitor wells (former and current). The OCD requires that Conoco include this information in future reports.
- 4. Some of the reports do not contain quarterly ground water potentiometric maps. The OCD requires that Conoco's future reports include ground water potentiometric maps for each sampling event. The maps will be created using the water table elevation in all site monitor wells.
- 5. Some of the report summary tables do not contain the results of all past water quality sampling. It is difficult for the OCD to evaluate remedial progress at a site without this data. The OCD requires that Conoco's future reports include summary tables that contain the results of all past and present water quality sampling.

If you have any questions, please call me at (505) 827-7154.

Sincerely,

William C. Olson Hydrologist Environmental Bureau

xc: Denny Foust, OCD Aztec District Office Larry Trujillo, On Site Technologies, Ltd.







FEB 27 1998

Environmental Caldu Oil Conservation Division

Letter of Transmittal

ATTENTION:

DATE: February 4, 1998

Mr. Bill Olson New Mexico Oil Conservation Division 2040 South Pacheco Santa Fe, New Mexico 87505

RE: Conoco's 1997 Annual Groundwater Report.

REMARKS:

Dear Mr. Olson:

On behalf of Conoco, **On Site Technologies Limited Partnership**, is submitting the enclosed 1997 Annual Groundwater report for the twelve (12) sites

We are sending you:

No. Originals	No. Copies Description
. 1	Farmington B Com 1, Unit H, Sec. 12, T29N, R12W
27 1	San Juan 28-7-19, Unit G, Sec. 25, T28N, R7W
1	San Juan 28-7-47, Unit A, Sec.20, T28N, R7W
1	San Juan 28-7-126, Unit M, Sec.1, T27N, R7W
1	San Juan 28-7-219, Unit N, Sec. 20, T28N, R7W
1	Shephard & Kelsey #1, Unit L, Sec. 29, T29N, R11W
1	Nell-Hall #1, Unit , Sec. 1, T30N, R11W
1	Farmington Com #1, Unit P, Sec. 11, T29N, R13W
1	Farmington C Com #1, Unit L, Sec. 15, T29N, R13W
1	Farmington B Com #1E, Unit O, Sec. 15, T29N, R13W
1	Salmon #1, Unit P Sec. 30, T29N, R11W
1	Shephard & Kelsey 1E, Unit D, Sec. 29, T29W, R11W

SIGNATURE:

Larry Trujillo Sr. Environmental Technician CC: Denny Foust Shirley Ebert Neal Goates



ANNUAL SUMMARY

PIT CLOSURES AND GROUND WATER IMPACT UPDATES

STATE OF NEW MEXICO 1996

RECEIVED

MAY 2 0 1997

Environmental Bureau Oil Conservation Division

Frech site seperate Aleu under seperate Aleu Ales Case



Midland Division Exploration Production Conoco Inc. 10 Desta Drive, Suite 100W Midland, TX 79705-4500 (915) 686-5400

Certified Mail P 895 104 872

April 25, 1997

Mr. Denny Fouts New Mexico Oil Conservation Commission 1000 Rio Brazos Rd. Aztec, NM 87410

Dear Mr. Fouts:

Re: NMOCD letters P-471-215-177, P-471-215-178 and P-471-215-179

Reference NMOCD letters of February 18, 1997 (P-471-215-177 and P-471-215-178) directed to Conoco Inc. and NMOCD letter of February 18, 1997 (P-471-215-179) directed to Merrion Oil and Gas Corporation.

This letter is intended to update NMOCD on the progress made to date to evaluate the alleged environmental contamination identified in the subject NMOCD letters. Evaluation work was timely commenced at all sites under Conoco's supervision. Initial results are being documented and evaluated. Where appropriate, possible remediation plans are being considered. As you are aware, ownership of the sites have changed hands several times, and we are in the process of developing proposed plans consistent with the contractual obligations of the successive owners. As soon as reasonably possible, NMOCD will be advised of proposed remediation plans where appropriate, to resolve the environmental matters addressed in the subject NMOCD letters.

Regards,

Carl J. Coy Field SHEAR Specialist

cc: Merrion Mesa Bill Olson - NMOCD Santa Fe

Table of Contents

1	1996 PIT CLOSURE SUMMARY DATA	
2	FARMINGTON COM #1	
3	FARMINGTON C COM #1	Γ
4	FARMINGTON B COM #1E	Γ
5	SMITH #1 & DRIP PIT	Γ
6	SHEPHERD & KELSEY #1	Γ
7	SHEPHERD & KELSEY #1E (DEHY/SEP PIT) PRODUCTION TANK LEAK)	
8	FARMINGTON B COM #1	
9	FEDERAL COM #15	
10	SALMON #1	
11	NELL HALL #1	
12	SAN JUAN 28-7 #19	
13	SAN JUAN 28-7 #47	
14	SAN JUAN 28-7 #126	
15	SAN JUAN 28-7 #219	

AVERY *

READY INDEX™ INDEXING SYSTEM



Revised: May 15, 1997

Conoco, Inc., Midland Division Exploration and Production, North America 10 Desta Drive, Suite 100W Midland, Texas 79705-4500

Attn.: Mr. Neal Goates, Senior Environmental Specialist

RE: Transmittal of Information for 1996 Annual NMOCD Reporting

Per your request and at Mr. C. John Coy's (Farmington Office) direction, we have compiled the attached information to assist you with the annual reporting to NMOCD. The information listed in Table 1 is included.

If there are any questions regarding this status report, please contact either Cindy Gray or Myke Lane at On Site Technologies, (505) 325-5667. Thank you for considering On Site to assist you with this matter.

Respectfully submitted, On Site Technologies Limited Partnership

Michael K. Lane, P.E. Senior Engineer

Enclosures: Table 1 & Listed Attachments

CC: C. John Coy (w/o attachments) MKL/mkl

file: 41303.doc

TABLE 1: CONCいO SUMMARY Transmittal of Information for 1996 Annual NMOCD Reporting

> On Site Technologies Limited Partnership May 15, 1997

Project: 4-1303

.

لحنيه	» Well	Date	Documents	Comments
	Farmington Com #1	Apr. 18, 97	Site Assessment Brief w/ lab and QA/QC	Corrective Action to address soil and/or ground water contamination pending negotiations with former lease operator.
)	Farmington C Com #1	Apr. 22, 97	Site Assessment Brief w/ lab and QA/QC	Corrective Action to address soil and/or ground water contamination pending negotiations with former lease operator.
1	Farmington B Com #1E	Apr. 22, 97	Site Assessment Brief w/ lab and QA/QC	Corrective Action to address soil and/or ground water contamination pending negotiations with former lease operator.
	Smith #1 & Drip Pit	Apr. 22, 97	Site Assessment Brief w/ lab and QA/QC	Corrective Action to address soil and/or ground water contamination pending negotiations with former lease operator.
	Shepherd & Kelsey #1	Mar. 21, 97 July 18, 96 Mar. 20, 97	Summary of Monitor Well Install & Map Sample Results w/ QA/QC (IML) Sample Results w/ QA/QC (On Site)	Continue ground water monitoring for 3 additional quarters to verify RBCA.
	Shepherd & Kelsey #1E (Dehy/Sep Pit)	Apr. 16, 97	Pit Assessment & Remediation Summary w/ lab and QA/QC	No further reclamation efforts recommended, and propose continued ground water monitoring until four consecutive sample events are "clean".
	Shepherd & Kelsey #1E (Production Tank Spill)	Apr. 28, 97	Spill Assessment & Remediation Summary w/ lab and QA/QC	No further corrective action, with plug and abandonment of monitor well proposed.
1	Farmington B Com #1	Apr. 16, 97	Investigation & Remediation Summary w/ lab and QA/QC	No further reclamation efforts recommended, and propose continued ground water monitoring until four consecutive sample events are "clean".
	Federal Com #15	Apr. 28,97	Site Assessment Summary	No further action.
	Salmon #1	May 12, 97 July 17, 96 Mar. 18, 96 Mar. 26, 97	Corrective Action Proposal (On Site) Lab Reports & QA/QC (IML) Lab Reports & QA/QC (On Site) Lab Reports & QA/QC (On Site)	Additional excavation and treatment of contaminated soil down-gradient of original pit proposed.

ĩ

On Site Technologies Limited Partnership May 15, 1997

Transmittal of Information for 1996 Annual NMOCD Reporting

i

Project: 4-1303

*

ļ

Well	Date	Documents	Comments
Nell Hall #1	June 14, 97		Due to seasonal low water table, propose annual sampling
	June 28, 96	Lab Reports & QA/QC (IML)	to be scheduled in June to Aug. with closure once two
	July 12, 96		consecutive sample events show "clean".
	Apr. 1, 97	Letter regarding no water (On Site)	
SJ 28-7 #19	Mar. 12, 96		Continue ground water monitoring for four additional
	July 17, 96	Lab Reports & QA/QC (IML)	quarters.
	Mar. 19, 97	Lab Reports & QA/QC (On Site)	
	Apr. 21, 97	Lab Reports & QA/QC (On Site)	
SJ 28-7 #47	Mar. 12, 96	Lab Reports & QA/QC (IML)	Continue ground water monitoring for four additional
	Apr. 15, 96	Lab Reports & QA/QC (IML)	quarters.
	July 17, 96	Lab Reports & QA/QC (IML)	
	Mar. 19, 97	Lab Reports & QA/QC (On Site)	
	Apr. 21, 97	Lab Reports & QA/QC (On Site)	
SJ 28-7 #126	Mar. 12, 96	Lab Reports & QA/QC (IML)	Continue ground water monitoring for an additional
	July 17, 96	Lab Reports & QA/QC (IML)	quarter.
	Mar. 26, 97	Lab Reports & QA/QC (On Site)	
SJ 28-7 #219	Mar. 12, 96	Lab Reports & QA/QC (IML)	Continue ground water monitoring for two additional
	July 17, 96	Lab Reports & QA/QC (IML)	quarters.
	Mar. 26, 97	Lab Reports & QA/QC (On Site)	

Page 2 of 2

-

'NEW MEXICO FIT DATA 'CONOCO INC.

...

ł

	BDP: Blowdown Pit FGP: Fiberglass Tank Pit LDHP: Lined Dehy Pit DRP: Drilling Reserve Pit NONE: No Pits
TYPES OF PITS	rubberPit
	SEP: Separator Ptt DHP: Dehydrator Ptt CSP: CompressorSc TDP: Tank Drip Ptt LDP: Line Drip Ptt

DATE PIT CLOSED	OF INCING	05/00/00	04/22/20	04/22/30	03/19/20	08/12/30	03/20/30			00/13/30	00/12/00			00/0//30	00/12/20	06/17/00	06/21/20	06/21/00	06/12/30	90/00/20		00/20/30	07/75/06	2012/10	042430	08/15/96	96/6/20	03/29/96	04/15/96	04/15/96	04/15/96	08/15/96	ACT 100		advinov	00/12/120	10,000		DR/h7/Rh
REMED- IATION STARTED																																							
STOPPED FLOW TO PIT		Unknown	Unknown	Unknown	09/10/96	03/27/96	03/18/96	Unknown	UNKNOWN	UNKNOWN	UNKNOWN	Unknown	UNKNOWI	UNKNOWN	Unknown	Unknown	Unknown	Unknown	Unknown	06/26/96						00/10/08	03/7/96	03/20/06	NAMA/96	04/00/02	04/12/06	027/00	2012/10		Ben Zin		11-1-1-1-1		
OTHER PARTY PIT																																							
NON- VULN. AREA																																							
EXPANDED VULN AREA		×	×	×	×	×	×	×	×	×	×	×	×	×	×	×	×	×	×	×	×	×	×	×	×	×	×	<>	<>	<)	×>	× >	×	×	×	×	×	×	×
VULN. AREA																																							
PIT SIZE		30' x 24' x 4'	18' x 17' x 3'	44' x 30' x 6'	37 x 36 x 3'	19' x 19' x 4'	18'X18'X3'	28' x 22' x 4'	10' x 8' x 3'	35 x 27 x 4'	21' x 20' x 4'	22' x 22' x 4'	18' x 16' x 4'	19' x 18' x 3'	18' x 17' x 4'	17 × 16 × 4'	19' × 17' × 4'	28' x 22' x 4'	25' x 25' x 4'	201/201/31	10'x10'x5'	16x16x4	16x16x4'	15/25/3	10'x15'x3'	15×15×2*	18'x18'x3'	16x18x4	12x12x2	12X14X4	16x18x3'	15×15×2	18'x18'x3'	10×10×3	10x12'x3'	12'x14'x3'	14'x16'x2'	12'x14'x4'	10x10x01'
TYPES OF PITS		SFP :	T	t	T	T	┢	T	1	SEP 3	SEP 2		TDP 1	SEP 1		T	T	Γ	TDP 2		TDP								SEP	٦		1							SEP 1
TON		WE-NAC-A	WE-N9C-D	L76N-3W	25N-5W	-25N-4W	2-25N-4W	-26N-4W	-26N-4W	-26N-4W	1-26N-4W	10-26N-4W	1-26N-4W	-26N-4W	1-26N-4W	WP-N9C-	-26N-4W	-26N-4W	-26N-4W	-26N-4W	4-26N-4W	3-26N-4W	3-26N-4W	5-26N-4W	5-26N-4W	-26N-4W	5-26N-4W	-26N-4W	-26N-4W	Sec 29-26N-3W	Sec 29-26N-3W	D-26N-3W	-26N-4W	-26N-4W	-26N-4W	-25N-5W	25N-5W	-25N-5W	WS-NSC-
LOCAT		Init D Car 15		Ulin D. Sec. 20-26N-3W	Init I Ser 6.	Init C Sec 1-	Init C Sec 12		Unit L Sec. 31-26N-4W	Unit L Sec. 32-26N-4W	Unit G Sec 30-26N-4W	Linit G. Sec. 3	Init G Sec 3	Unit P. Sec. 31-26N-4W	Unit P. Sec. 31	at R Sec 3	Lint B Sec 32-26N-4W	Init i Sec 37.	Unit I Sec 32.	Unit E. Sec 23-26N-4W	Unit C. Sec 14	nit D. Sec 23	Unit E. Sec 13	Unit K. Sec 25	Unit K, Sec 25	Unit K, Sec 26-26N-4W	Unit D, Sec 26	Unit M, Sec 36-26N-4W	Unit J, Sec 36-	Unit A, Sec 29	Unit D, Sec 29	Unit A, Sec 30	Unit B, Sec 21	Unit C, Sec 15-26N-4W	Unit D. Sec 15-26N-4W	Unit M, Sec 02-25N-5W	Unit 1, Sec 01-25N-5W	Unit M. Sec 02-25N-5W	nt O Sec 03
, STATE JAN KCT NO FEE				T				Ī				T	T			T		T	T						Γ											Г	T		Г
FEDERAL, STATE INDIAN CONTRACT NO. OR FEE	ARILLA	100000000000000000000000000000000000000	Contract #	Contract #08	Collicaci #147	Contract #121	Contract #101	Contract #12	Contract #12	Contract #12	Contract #12	Contract #12	Contract #10	Contract #12	Contract #12	Contract #12		Contract #10	Contract #12	Contract # 105	Contract # 105	Contract # 105	Contract # 105	Contract # 106	Contract # 106	Contract # 106	Contract # 106	Contract # 106	Contract # 106	Contract # 100	Contract # 100	Contract # 100	Contract # 104	Contract # 104	Contract # 104	Contract No. 145	Contract No. 145	Contract No. 145	Contract No 145
WELL NAME AND NUMBER	SENSITIVE AREA PITS - JICARILLA		NO. 1	NO. 3E	NO. 7	AXI Apache J NO. 22	AXI Apache N No. 14	0 AXI ADACITE N NO. 100	NO. 0	No. 8	No. 0	NO. 11	NU. 11	NO. 13	NO. 14	NO. 14	NO. 17	NO. 17	NO. 10	A NO. 10	A NO O	JICATINA A NO. 3 Licarita A No. 10	Jicarila A No. 13		A NO A	B No. 9	Jicarilla B No. 9A	Jicarila B No. 13	Jicarila B No. 15	D No 11	licarila D No 17	licarila D No 18	E No 6	E No 8	liccits E No. 14	JICATINA E NO. 14 licarita K No. 12F	licarita K No. 15	licelle V No. 22	N NU. 44
	SENSITI					4 AXI Apa	S AXI Apac	7 liantila No 3		O licarilla No. 4		14 Hondrilla No. 1			13 JICATINA NO. 14	14 JICATHIA	15 JICarilla No. 1/	10 JICATINA NO. 1/	1/ JICARNIA NO. 10	10 licarila NO. 10	DO LICETHA A NO O	20 JICarlia	21 Jicarilla	22 Jucanilla A No. 7	24 licarilla B No. 8	25 Licarila B No. 9	26 Jicarilla	27 Jicarilla	28 Jicarilla	20 Jicarilla D No 11	30 Jicarila							SO UNCERTING	3/ JICHING N NU. 22

05/06/96	05/06/96		03/22/96	03/29/96	03/22/96	03/26/96	03/29/96	03/25/96	04/22/96	04/22/96	04/22/96	06/03/96	05/03/96
Unknown	Unknown		Unknown	03/22/96	Unknown	03/25/96	03/25/96	03/20/96	04/19/96	04/16/96	04/15/96	04/25/96	04/25/96
			×	×	×	×	×	×	×	×	×	×	×
×	×												
30' x 24' x 6'	24' × 17' × 4'		22' x 19' x 3'	21' x 21' x 4'	19'X19'X3'	20' x 18' x 3'	22' x 21' x 3'	23' x 21' x 3'	16×16×3	15×15×2	2012012	25'28'22'	201/201/4
SEP	TDP		SEP	SEP	SEP	SEP	SEP	SEP	401	401	SEP	dQL	TDP
Unit L, Sec. 9-26N-3W	Unit L, Sec. 9-26N-3W		Unit B, Sec. 12-25N-4W	Unit L. Sec. 11-25N-4W	Unit K, Sec. 1-25N-4W			Unit J, Sec. 3-25N-4W	104	Unit A. Sec 32-26N-3W	Unit P, Sec 32-26N-3W	Unit I, Sec 31-26N-3W	Unit N. Sec 31-26N-3W
Fed. 6090001150 Unit L, Sec.	Fed. 6090001150 Unit L, Sec.	TS - JICARILLA	Contract #121	Contract #121	Contract #121	Contract #121	Contract #121	Contract #122	Contract # 100	Γ		Γ	Γ
39 Tribal No. 2	40 [Tribal No. 2	NON - SENSITIVE AREA PITS - JICARILLA	1 AXI Apache N No. 11A	2 AXI Apache N No. 12A	3 AXI Apache N No.14A	4 AXI Apache N No. 12	5 AXI Apache N No. 13	6 AXI Apache O No. 10	7 Jicarilla D No. 11A	8 Jicarilla D No. 13	9 Jicarilla D No. 13A	10 Jicarilla D No. 19	11 Jicarilla D No. 20

.

į



STATE OF NEW MEXICO

ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION 2040 S. PACHECO SANTA FE, NEW MEXICO 87505 (505) 827-7131

January 31, 1997

<u>CERTIFIED MAIL</u> <u>RETURN RECEIPT NO. P-269-269-243</u>

Mr. Neal Goates Conoco Inc. 10 Desta Drive, Suite 100W Midland, Texas 79705-4500

RE: GROUND WATER CONTAMINATION ASSESSMENT SAN JUAN 28-7 UNIT WELLS #219, #47, #19, **W226**

Dear Mr. Goates:

The New Mexico Oil Conservation Division (OCD) has completed a review of the following Conoco documents:

- October 15, 1996 "GROUNDWATER ASSESSMENT PROPOSAL, SAN JUAN 28-7 WELLS #219 (S20, TNW28 R7W UNIT A), #47 (S20 TNW28 R7W UNIT A), #19 (S25, TNW28, R7W UNIT G), #126 (S1 TNW28 R7W UNIT M)".
- Undated "CONOCO SAN JUAN 28-7 LEASE, WELLS 219, 19, 47, 126" which was received by the OCD on September 16, 1996.

These documents contain the results of Conoco's investigation of the extent of contamination resulting from disposal of production wastes in unlined pits at Conoco's San Juan 28-7 Unit wells #219 (Unit N, Sec. 20, T28N, R07W), #47 (Unit A, Sec. 20, T28N, R07W), #19 (Unit G, Sec. 25, T28N, R07W) and #126 (Unit M, Sec. 01, T27N, R7W). The documents also contain recommendations for ground water quality monitoring of the existing monitor wells until New Mexico Water Quality Control Commission (WQCC) ground water standards are met and installation of no further monitor wells based upon the results of a risk assessment.

The OCD's review of the above referenced documents is addressed below.

- A. Based upon the current non-detectable concentrations of petroleum compounds at the San Juan 28-7 Unit wells #219, #19 and #126, Conoco's recommendations for these sites are approved with the following conditions:
 - 1. All ground water sampling and analysis will be conducted using EPA approved methods.

Mr. Neal Goates January 31, 1997 Page 2

- 2. While site monitoring is ongoing, Conoco will submit a separate annual report for each site to the OCD by April 1 or each year. The reports will contain:
 - a. A description of the monitoring activities during the past year including conclusions and recommendations.
 - b. A summary of past and present analytical results of all ground water monitoring for each site including copies of the laboratory analyses and associated quality assurance/quality control data.
- 3. Ground water quality monitoring will not be considered complete until water quality samples from the monitor wells are shown to be below WQCC standards for four (4) consecutive quarters.
- 4. Upon completion of ground water actions, Conoco will submit to the OCD for approval final pit closure reports for each site which will contain the results of all remedial actions and monitoring.

Please be advised that OCD approval does not relieve Conoco of liability if implementation of the recommendations fails to adequately monitor ground water contamination at the sites. In addition, OCD approval does not relieve Conoco of responsibility for compliance with any other federal, state, tribal or local laws and/or regulations.

B. Due to concentrations of benzene in ground water in excess of WQCC standards at the San Juan Unit 28-7 well #47, the OCD defers approval of Conoco's recommendations for this site until Conoco provides the OCD with actual field data which verifies the model results. The field verification data will be submitted to the OCD by March 28, 1997.

If you have any questions, please call me at (505) 827-7154.

Sincerely,

William C. Olson Hydrogeologist Environmental Bureau

xc: OCD Aztec District Office Bill Liess, BLM Farmington District



Midland Division Exploration Production **Conoco Inc.** 10 Desta Drive, Suite 100W Midland, TX 79705-4500 (9.15) 686-5400

October 15, 1996

William C. Olson Environmental Bureau New Mexico Oil Conservation Division 2040 S. Pacheco Santa Fe, New Mexico 87505

Dear Mr. Olson:

GOUNDWATER ASSESSMENT PROPOSAL, SAN JUAN 28-7 WELLS #219 (S20, TNW28 R7W UNIT A), #47 (S20 TNW28 R7W UNIT A), #19 (S25, TNW28, R7W UNIT G), **#126** (S1 TNW28 R7W Unit M).

INTRODUCTION

This letter is the follow up recommendation after the meeting between Conoco and the NMOCD held on September 16, 1996. Please disregard previous letter dated October 1. During the course of pit assessment work in the expanded vulnerable area Conoco identified groundwater contamination at these sites. Please note that the site investigation went beyond NMOCD's proposed scope of phase II assessment in determining vertical extent of the contamination outlined in Section II <u>SOIL AND</u> WATER REMEDIATION LEVELS subheading A SOILS part 2b Recommended Remediation Level.

RECOMMENDATION

Please attach this letter with the risk assessment work completed for the subject properties. Based on the risk analysis output, Conoco recommends that no additional monitoring wells will be needed. The Tier 1 lookup table values indicates that wells 219, 19, and 126 are below the Risk-Based Screening Level for Benzene. In addition, Tier II modeling for well 47 clearly demonstrates that off-site transport is not a concern and concentration of Benzene for anticipated use of area would not be a future health threat for residential use of the property. Conoco will utilized our existing monitor wells located adjacent and down gradient of the original pit locations for progress toward natural biodegradation. We will sample the monitor wells for BTEX content on an annual basis and forward the results with our annual pit closure progress report. The sites will seek individual approval for closure when the BTEX analysis results are below the MCL for each constituent of concern for a minimum of two sample events within the frequency of one full year. The soil within the pit area will be delineated and remediated using the current approved methods for pit closure (OVM screening, excavation, surface remediation, analytical based closure).

WORK SUMMARY

With the assistance of Western Technologies boring crew and geologist, our Conoco representative organized the task of determine the subsurface vertical extent of the soil contamination by the use of a geoprobe adjacent and down gradient from the unlined surface impoundment and sampled with a calibrated PID meter in accordance with Sections V-IX. The subjects soil contamination surpassed the closure guidelines of 100 ppm and also exceeded the vertical limits of the geoprobe at 40'. It was

decided by our site supervisor to continue the borings with a hollow stem auger regardless of formation changes (sandstone) until such drilling was impeded, OVM readings were extensively below 100 ppm, or groundwater was encountered. The monitor wells were completed according to OCD requirements and adequately purged for water analysis. The analysis concluded that BTEX readings exceeded the closure standard set by the New Mexico WQCC. The attached logs define the PID readings corrected for Benzene and complete analysis accompany the risk assessment report.

Sincerely,

Neal Goates Environmental Specialist

cc: Denny Foust, OCD Aztec Office John Coy, Conoco Farmington



Midland Division Exploration Production

Conoco Inc. 10 Desta Drive, Suite 100W Midland, TX 79705-4500 (915) 686-5400

106 00 17 EN 0 52

October 1, 1996

William C. Olson Environmental Bureau New Mexico Oil Conservation Division 2040 S. Pacheco Santa Fe, New Mexico 87505

Dear Mr. Olson:

GOUNDWATER ASSESSMENT PROPOSAL, SAN JUAN 28-7 WELLS #219 (S20, TNW28 R7W UNIT A), #47 (S20 TNW28 R7W UNIT A), #19 (S25, TNW28, R7W UNIT G), #126 (S1 TNW28 R7W Unit M).

INTRODUCTION

This letter is the follow up recommendation after the meeting between Conoco and the NMOCD held on September 16, 1996. During the course of pit assessment work in the expanded vulnerable area Conoco identified groundwater contamination at these sites. Please note that the site investigation went beyond NMOCD's proposed scope of phase II assessment in determining vertical extent of the contamination outlined in Section II <u>SOIL AND WATER REMEDIATION LEVELS</u> subheading A SOILS part 2b Recommended Remediation Level.

RECOMMENDATION

Please attach this letter with the risk assessment work completed for the subject properties. Conoco will utilized our existing monitor wells located adjacent and down gradient of the original pit locations for progress toward natural biodegradation. We will sample the monitor wells for BTEX content on an annual basis and forward the results with our annual pit closure progress report. The sites will seek individual approval for clocure when the BTEX analysis results are below the MCL for each constituent of concern for a minimum of two sample events within the frequency of one full year. The soil within the pit area will be delineated and remediated using the current approved methods for pit closure (OVM screening, excavation, surface remediation, analytical based closure).

WORK SUMMARY

With the assistance of Western Technologies boring crew and geologist, our Conoco representative

organized the task of determine the subsurface vertical extent of the soil contamination by the use of a geoprobe adjacent and down gradient from the unlined surface impoundment and sampled with a calibrated PID meter in accordance with Sections V-IX. The subjects soil contamination surpassed the closure guidelines of 100 ppm and also exceeded the vertical limits of the geoprobe at 40'. It was

decided by our site supervisor to continue the borings with a hollow stem auger regardless of formation changes (sandstone) until such drilling was impeded, OVM readings were extensively below 100 ppm, or groundwater was encountered. The monitor wells were completed according to OCD requirements and adequately purged for water analysis. The analysis concluded that BTEX readings exceeded the closure standard set by the New Mexico WQCC. The attached logs define the PID readings corrected for Benzene and complete analysis accompany the risk assessment report.

Sincerely,

Neal Goates Environmental Specialist

cc: Denny Foust, OCD Aztec Office John Coy, Conoco Farmington



SAN JUAN 28-7 LEASE

WELLS 219, 19, 47, #126

PEACIVED

SEP 1 6 1996

Environmental Bureau Oil Conservation Division





ANNUAL SUMMARY

PIT CLOSURES AND GROUND WATER IMPACT UPDATES

STATE OF NEW MEXICO 1996

RECEIVED

MAY 2 0 1997

Environmental Bureau Oil Conservation Division

Frech site seperate Aleu under seperate Aleu Ale.s



Midland Division Exploration Production

Conoco Inc. 10 Desta Drive, Suite 100W Midland, TX 79705-4500 (915) 686-5400

Certified Mail P 895 104 872

April 25, 1997

Mr. Denny Fouts New Mexico Oil Conservation Commission 1000 Rio Brazos Rd. Aztec, NM 87410

Dear Mr. Fouts:

Re: NMOCD letters P-471-215-177, P-471-215-178 and P-471-215-179

Reference NMOCD letters of February 18, 1997 (P-471-215-177 and P-471-215-178) directed to Conoco Inc. and NMOCD letter of February 18, 1997 (P-471-215-179) directed to Merrion Oil and Gas Corporation.

This letter is intended to update NMOCD on the progress made to date to evaluate the alleged environmental contamination identified in the subject NMOCD letters. Evaluation work was timely commenced at all sites under Conoco's supervision. Initial results are being documented and evaluated. Where appropriate, possible remediation plans are being considered. As you are aware, ownership of the sites have changed hands several times, and we are in the process of developing proposed plans consistent with the contractual obligations of the successive owners. As soon as reasonably possible, NMOCD will be advised of proposed remediation plans where appropriate, to resolve the environmental matters addressed in the subject NMOCD letters.

Regards,

Carl J. Coy Field SHEAR Specialist

cc: Merrion Mesa Bill Olson - NMOCD Santa Fe

Table of Contents

	NELL HALL #1	
10	SALMON #1	
9	FEDERAL COM #15	
7 8	(DEHY/SEP PIT) PRODUCTION TANK LEAK)	
6	SHEPHERD & KELSEY #1 SHEPHERD & KELSEY #1	
5	SMITH #1 & DRIP PIT	
4	FARMINGTON B COM #1E	ſ
3	FARMINGTON C COM #1	⊥ 「
1	1996 PIT CLOSURE SUMMARY DATA FARMINGTON COM #1	_ г

AVERY .

On Site Technologies Limited Partnership May 15, 1997

Transmittal of Information for 1996 Annual NMOCD Reporting

Project: 4-1303

* Well	Date	Documents	Comments
Farmington Com #1	Apr. 18, 97	Site Assessment Brief w/ lab and QA/QC	Corrective Action to address soil and/or ground water contamination pending negotiations with former lease operator.
Farmington C Com #1	Apr. 22, 97	Site Assessment Brief w/ lab and QA/QC	Corrective Action to address soil and/or ground water contamination pending negotiations with former lease operator.
Farmington B Com #1E	Apr. 22, 97	Site Assessment Brief w/ lab and QA/QC	Corrective Action to address soil and/or ground water contamination pending negotiations with former lease operator.
Smith #1 & Drip Pit	Apr. 22, 97	Site Assessment Brief w/ lab and QA/QC	Corrective Action to address soil and/or ground water contamination pending negotiations with former lease operator.
Shepherd & Kelsey #1	Mar. 21, 97 July 18, 96 Mar. 20, 97	Summary of Monitor Well Install & Map Sample Results w/ QA/QC (IML) Sample Results w/ QA/QC (On Site)	Continue ground water monitoring for 3 additional quarters to verify RBCA.
Shepherd & Kelsey #1E (Dehy/Sep Pit)	Apr. 16, 97	Pit Assessment & Remediation Summary w/ lab and QA/QC	No further reclamation efforts recommended, and propose continued ground water monitoring until four consecutive sample events are "clean".
Shepherd & Kelsey #1E (Production Tank Spill)	Apr. 28, 97	Spill Assessment & Remediation Summary w/ lab and QA/QC	No further corrective action, with plug and abandonment of monitor well proposed.
Farmington B Com #1	Apr. 16, 97	Investigation & Remediation Summary w/ lab and QA/QC	No further reclamation efforts recommended, and propose continued ground water monitoring until four consecutive sample events are "clean".
Federal Com #15	Apr. 28,97	Site Assessment Summary	No further action.
Salmon #1	May 12, 97 July 17, 96 Mar. 18, 96 Mar. 26, 97	Corrective Action Proposal (On Site) Lab Reports & QA/QC (IML) Lab Reports & QA/QC (On Site) Lab Reports & QA/QC (On Site)	Additional excavation and treatment of contaminated soil down-gradient of original pit proposed.

l

1

)

١

Page 1 of 2

On Site Technologies Limited Partnership May 15, 1997

Project: 4-1303

Transmittal of Information for 1996 Annual NMOCD Reporting

د.

Well	Date	Documents	Comments
Nell Hall #1	June 14, 97	Lab Reports & QA/QC (IML)	Due to seasonal low water table, propose annual sampling
	June 28, 96	Lab Reports & QA/QC (IML)	to be scheduled in June to Aug. with closure once two
	July 12, 96	Lab Reports & QA/QC (IML)	consecutive sample events show "clean".
	Apr. 1, 97	Letter regarding no water (On Site)	
SJ 28-7 #19	Mar. 12, 96	Lab Reports & QA/QC (IML)	Continue ground water monitoring for four additional
	July 17, 96	Lab Reports & QA/QC (IML)	quarters.
	Mar. 19, 97	Lab Reports & QA/QC (On Site)	
	Apr. 21, 97	Lab Reports & QA/QC (On Site)	
SJ 28-7 #47	Mar. 12, 96	Lab Reports & QA/QC (IML)	Continue ground water monitoring for four additional
	Apr. 15, 96	Lab Reports & QA/QC (IML)	quarters.
	July 17, 96	Lab Reports & QA/QC (IML)	
	Mar. 19, 97	Lab Reports & QA/QC (On Site)	
	Apr. 21, 97	Lab Reports & QA/QC (On Site)	
SJ 28-7 #126	Mar. 12, 96	Lab Reports & QA/QC (IML)	Continue ground water monitoring for an additional
	July 17, 96	Lab Reports & QA/QC (IML)	quarter.
	Mar. 26, 97	Lab Reports & QA/QC (On Site)	
SJ 28-7 #219	Mar. 12, 96	Lab Reports & QA/QC (IML)	Continue ground water monitoring for two additional
	July 17, 96	Lab Reports & QA/QC (IML)	quarters.
	Mar. 26, 97	Lab Reports & QA/QC (On Site)	

Page 2 of 2

05/06/96	05/06/96		03/22/96	03/29/96	03/22/96	03/26/96	03/29/96	03/25/96	04/22/96	04/22/96	04/22/96	05/03/96	05/03/96
Unknown	Unknown		Unknown	03/22/96	Unknown	03/25/96	03/25/96	03/20/96	04/19/96	04/16/96	04/15/96	04/25/96	04/25/96
			×	×	×	×	×	×	×	×	×	×	×
×	×												
30' x 24' x 6'	24' x 17' x 4'		22' x 19' x 3'	21' x 21' x 4'	19'x19'x3'	20' x 18' x 3'	22' x 21' x 3'	23' x 21' x 3'	16×16×3	15×15×2	2012012	25/28/22	20530x4
SEP	TDP		SEP	SEP	SEP	SEP	SEP	SEP	TDP	TOP	SEP	TDP	TDP
Unit L, Sec. 9-26N-3W	Unit L, Sec. 9-26N-3W		Unit B. Sec. 12-25N-4W	Unit L. Sec. 11-25N-4W	-		Unit G. Sec. 2-25N-4W	Unit J. Sec. 3-25N-4W	Unit P. Sec 29-26N-3W	Unit A. Sec 32-26N-3W	Unit P. Sec 32-26N-3W	Unit I, Sec 31-26N-3W	Unit N. Sec 31-26N-3W
Fed. 6090001150 Unit L, Sec.	Fed. 6090001150 Unit L, Sec.	TS - JICARILLA	Contract #121	Contract #121	Contract #121	Contract #121					Contract # 100	Contract # 100	Contract # 100
39 Tribal No. 2	40 Tribal No. 2	NON - SENSITIVE AREA PITS - JICARILLA	1 AXI Apache N No. 11A	2 AXI Apache N No. 12A	3 AXI Apache N No.14A	4 AXI Apache N No. 12	5 AXI Apache N No. 13	6 AXI Apache O No. 10	7 Jicarilla D No. 11A	8 Jicarilla D No. 13	9 Jicarilla D No. 13A	10 Jicarilla D No. 19	11 Jicarila D No. 20

. . ,

-. ı