

3R - 318

APPROVALS

YEAR(S):

2003-1997



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Lori Wrotenbery

Director

Oil Conservation Division

June 11, 2003

Mr. Mark B. Harvey
Williams Field Services
188 County Rd. 4900
Bloomfield, New Mexico 87413

**RE: CASE #3R-318
FLORANCE #124 SEPARATOR/DEHY PIT
SAN JUAN COUNTY, NEW MEXICO**

Dear Mr. Harvey:

The New Mexico Oil Conservation Division (OCD) has completed a review of Williams Field Services' (WFS) May 5, 2003 "CASE #3R0318 FLORANCE #124 SEPARATOR/DEHY PIT SAN JUAN COUNTY" and January 24, 2003 "FLORANCE #124 PIT REMEDIATION AND CLOSURE REPORT". These documents contain results of WFS's soil and ground water remediation of an unlined pit at the Florance #124 separator/dehy pit site located in Unit C, Sec. 27, T29N, R09W, San Juan County, New Mexico. The documents also request final closure approval of the site remedial actions.

The pit closure/remediation activities for this site are approved on the condition that the monitor wells are plugged and abandoned by cutting the casing off below ground surface and filling the annulus from bottom to top with a cement grout containing 3-5% bentonite. Please be advised that OCD approval does not relieve WFS of responsibility if remaining contaminants are found to pose a future threat to surface water, ground water, human health or the environment. In addition, OCD approval does not relieve WFS of responsibility for compliance with any other federal, state, tribal or local laws and regulations.

If you have any questions, please contact me at (505) 476-3491.

Sincerely,

William C. Olson

Hydrologist

Environmental Bureau

cc: Denny Foust, OCD Aztec District Office
Bill Liess, BLM Farmington District Office
Mike Lane, Williams Field Services



STATE OF NEW MEXICO
ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

2040 S. PACHECO
SANTA FE, NEW MEXICO 87505
(505) 827-7131

July 9, 1997

CERTIFIED MAIL
RETURN RECEIPT NO. P-410-431-188

Mr. Denver Bearden
PNM Gas Services
P.O. Box 4750
Farmington, NM 87499

RE: FINAL SAN JUAN BASIN PIT CLOSURE REPORTS

Dear Mr. Bearden

The New Mexico Oil Conservation Division (OCD) has completed a review of PNM Gas Services' (PNM) April 28, 1997 "OCD PIT CLOSURE REPORTS, 1ST REPORTING QUARTER 1997" and June 30, 1997 "OCD PIT CLOSURE REPORTS, 1ST REPORTING QUARTER 1997". These documents contain "PIT REMEDIATION AND CLOSURE REPORTS" for 48 unlined pits in the San Juan Basin of Northwestern New Mexico.

The OCD's review of the above referenced document is addressed below:

A. The pit closure/soil remediation activities conducted at the sites listed below are **approved**.

- | | |
|--|------------------------------|
| 1. Calloway #1A (Dehy pit) | Unit C, Sec. 22, T31N, R11W. |
| 2. Crandell #2 (Dehy pit) | Unit G, Sec. 19, T31N, R10W. |
| 3. Day Federal #1R (Dehy pit) | Unit L, Sec. 20, T28N, R10W. |
| 4. Federal A#1 (Dehy pit) | Unit M, Sec. 25, T30N, R13W. |
| 5. Federal A#1E (Dehy pit) | Unit O, Sec. 25, T30N, R13W. |
| 6. Federal A#2 (Dehy pit) | Unit G, Sec. 25, T30N, R13W. |
| 7. Federal A#3 (Dehy pit) | Unit A, Sec. 26, T30N, R13W. |
| 8. Federal A#3E (Dehy pit) | Unit P, Sec. 26, T30N, R13W. |
| 9. Federal Gas Com #2 (Drip pit) | Unit M, Sec. 27, T28N, R10W. |
| 10. Florance #41A (Dehy/inactive pit) | Unit J, Sec. 21, T29N, R09W. |
| 11. Florance AA #14A (Dehy/inactive pit) | Unit C, Sec. 08, T30N, R09W. |
| 12. Florance H #37A (Dehy pit) | Unit J, Sec. 06, T30N, R08W. |
| 13. Florance P#39A (Dehy pit) | Unit L, Sec. 35, T30N, R09W. |
| 14. Giomi GC C#1 (Drip pit) | Unit M, Sec. 28, T30N, R09W. |

Mr. Denver Bearden

July 9, 1997

Page 2

15. Hampton #4 (Dehy pit)	Unit D, Sec. 13, T30N, R11W.
16. Howell #1 (Dehy pit)	Unit K, Sec. 20, T30N, R08W.
17. Jacques #1 (Dehy pit)	Unit M, Sec. 25, T30N, R09W.
18. Jacques #1A (Dehy/separator pit)	Unit P, Sec. 25, T30N, R09W.
19. JF Day C#2 (Drip pit)	Unit P, Sec. 20, T28N, R10W.
20. JF Day D#1E (Separator/drip pit)	Unit P, Sec. 20, T28N, R10W.
21. Kutz Deep Gas Com D#1E (Dehy pit)	Unit I, Sec. 27, T28N, R10W.
22. Kutz J Federal #1 (Drip pit)	Unit B, Sec. 01, T27N, R10W.
23. Langendorf #1-34 (Dehy pit)	Unit A, Sec. 34, T31N, R13W.
24. Lester #1 (Dehy pit)	Unit H, Sec. 03, T30N, R11W.
25. Marie #1 South Main Line Drip (Drip pit)	Unit M, Sec. 13, T28N, R11W.
26. Marie #1 (Separator pit)	Unit J, Sec. 13, T28N, R11W.
27. McClanahan #14 (Drip pit)	Unit M, Sec. 23, T28N, R10W.
28. McClanahan #14E (Dehy pit)	Unit E, Sec. 23, T28N, R10W.
29. McClanahan A#1 (Separator pit)	Unit M, Sec. 23, T28N, R10W.
30. McClanahan A#3 (Separator pit)	Unit M, Sec. 23, T28N, R10W.
31. McDaniel C #1E (Separator pit)	Unit E, Sec. 19, T29N, R11W.
32. Mexico Federal K#1 (Separator pit)	Unit M, Sec. 09, T28N, R10W.
33. Miller Gas Com #1 (Drip pit)	Unit B, Sec. 21, T30N, R13W.
34. Newman C #1E (Separator pit)	Unit E, Sec. 30, T28N, R10W.
35. Olmer A #2E (Drip pit)	Unit F, Sec. 35, T28N, R10W.
36. Olmer A#6 (Separator pit)	Unit G, Sec. 36, T28N, R10W.
37. Olmer A#2 (Separator pit)	Unit G, Sec. 35, T28N, R10W.
38. Olmer #5 (Separator/drip pit)	Unit F, Sec. 26, T28N, R10W.
39. Olmer A#1E (Separator pit)	Unit F, Sec. 26, T28N, R10W.
40. Olmer A#2E (Separator pit)	Unit D, Sec. 35, T28N, R10W.
41. Olmer A#7E (Dehy pit)	Unit K, Sec. 36, T28N, R10W.
42. Phillips #1 (Dehy pit)	Unit I, Sec. 23, T31N, R13W.
43. Pierce #1A (Dehy pit)	Unit O, Sec. 30, T31N, R10W.
44. Pierce #2A (Dehy pit)	Unit E, Sec. 30, T31N, R10W.
45. Scott Federal #3 (Drip pit)	Unit C, Sec. 26, T27N, R11W.
46. State Com #1X (Dehy pit)	Unit N, Sec. 36, T32N, R12W.
47. Templeton #1E (Dehy pit)	Unit B, Sec. 27, T31N, R13W.

Please be advised that OCD approval does not relieve PNM of liability if remaining contaminants are found to pose a future threat to surface water, ground water, human health or the environment. In addition, OCD approval does not relieve PNM of responsibility for compliance with any other federal, state or local laws and/or regulations.

Mr. Denver Bearden

July 9, 1997

Page 3

- B. According to the report for the site listed below, ground water downgradient of PNM's pit is contaminated with benzene, toluene, ethylbenzene and xylene (BTEX) in excess of New Mexico Water Quality Control Commission (WQCC) ground water standards and upgradient ground water is contaminated with total dissolved solids (TDS) well in excess of 10,000 mg/l. PNM concludes that the upgradient TDS ground water concentrations makes the ground water unprotectable under state regulations and requests closure without remediation of the BTEX contaminants in the ground water.


Ground water is considered to have no beneficial use if it is naturally contaminated with TDS in excess of 10,000 mg/l. To date, the OCD has not encountered naturally occurring levels of TDS above 10,000 mg/l in this area and the OCD is concerned that these TDS levels may be the result of other contaminant source areas. Therefore, approval of the pit closure actions at this site are **denied** until the OCD can investigate the site for additional source areas and determine if the upgradient ground water quality is naturally contaminated with high levels of TDS. In the interim, the OCD requires that PNM continue to sample and analyze the ground water at the site for contaminants related to PNM's activities according to their previously approved ground water management plan..

1. Florance #124 (Dehy pit)

Unit D, Sec. 05, T30N, R10W.

If you have any questions, please call me at (505) 827-7154.

Sincerely,



William C. Olson
Hydrogeologist
Environmental Bureau

xc: OCD Aztec District Office
Bill Liess, BLM Farmington District Office