

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Incident ID	NRM2002449868
District RP	
Facility ID	
Application ID	

## Release Notification

### Responsible Party

Responsible Party Oxy USA Inc	OGRID 16696
Contact Name Eric Maestas	Contact Telephone 575-420-7825
Contact email <a href="mailto:Eric.Maestas@oxy.com">Eric.Maestas@oxy.com</a>	Incident # NRM2002449868
Contact mailing address PO Box 303 Amistad NM 88410	

### Location of Release Source

Latitude 35.953225 Longitude -103.630838  
(NAD 83 in decimal degrees to 5 decimal places)

Site Name 2033-221G	Site Type Well Gathering Line
Date Release Discovered 12/09/2019	API# (if applicable) 30-021-20460

Unit Letter	Section	Township	Range	County
G	22	20	33	Harding

Surface Owner: ☐ State ☐ Federal ☐ Tribal ☒ Private (Name: James Bradshaw)

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Natural Gas	Volume Released (Mcf) 999.57mcf	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release: Internal corrosion on 24" steel line. Line was depressurized and repaired

State of New Mexico  
Oil Conservation Division

Incident ID	NRM2002449868
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?

☐ Yes ☒ No

If YES, for what reason(s) does the responsible party consider this a major release?

If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?

## Initial Response

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

- ☒ The source of the release has been stopped.
- ☒ The impacted area has been secured to protect human health and the environment.
- ☐ Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.
- ☐ All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why: Items not checked were no applicable to Gas release.

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Eric Maestas

Title: HES Specialist

Signature: 

Date: 01/29/2020

email: Eric-Maestas@oxy.com

Telephone: 575-420-7825

### OCD Only

Received by: Ramona Marcus

Date: 2/5/2020