District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NRM2006340822
District RP	
Facility ID	
Application ID	

Release Notification

			Res	sponsi	bie Party	Y	
Responsible Party Marathon Oil Permian LLC			OGRID 37	72098			
Contact Name Melodie Sanjari			Contact Telephone 575-988-8753				
Contact email msanjari@marathonoil.com			Incident # (assigned by OCD)				
Contact mai	ling address	4111 S. Tidwell	Rd., Carlsbad, NI	M 8220			
Latitude 32.	19502018		Longitude		elease So -103.435907 grees to 5 decim	<u>735</u>	
Site Name: I	Dee Boot Fee	24 34 26 #3 #6 #	‡7 #19 CTB		Site Type C	Central Tank Battery	
Date Release	Discovered	2/26/2020			API# (if appl	licable) N/A	
Unit Letter	Section	Township	Range		Coun	ıty	
A	26	24S	34E	Lea			
Surface Owne	er: State	Federal 1	Tribal ⊠ Private Nature ai			Release)
		al(s) Released (Select	all that apply and atta	ich calculat	ions or specific	justification for the volumes provided belo	w)
Crude Oi	i1	Volume Releas	ed (bbls) 91.58			Volume Recovered (bbls) 85	
Produced	l Water	Volume Releas	ed (bbls)			Volume Recovered (bbls)	
Is the concentration of dissolved chlorid			e in the	☐ Yes ☐ No			

Cause of Release

Other (describe)

Condensate

Natural Gas

Volume Released (bbls)

Volume Released (Mcf)

Volume/Weight Released (provide units)

A gasket failure caused the release of approximately 91.58 bbls crude oil from the heater treater on the edge of containment, onto the engineered pad, across the entrance to the facility and an overspray to the pasture to the south. Initial response included source isolation and elimination, the recovery of approx. 85 bbls and the surficial scrape of the release area.

Volume Recovered (bbls)

Volume Recovered (Mcf)

Volume/Weight Recovered (provide units)

- 73			-		~
·	an	ra	٠,	a	•
	uz		- Au	v	, .
	- 0				


	- "8" - "J
Incident ID	NRM2006340822
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the response >25 bbls	sible party consider this a major release?
⊠ Yes □ No		
	otice given to the OCD? By whom? To who MOC) on 2/27/2020 via email to District II	om? When and by what means (phone, email, etc)?
	Initial Re	sponse
The responsible p	party must undertake the following actions immediately	unless they could create a safety hazard that would result in injury
	ase has been stopped.	
∑ The impacted area ha	s been secured to protect human health and t	he environment.
Released materials ha	we been contained via the use of berms or di	kes, absorbent pads, or other containment devices.
All free liquids and re	ecoverable materials have been removed and	managed appropriately.
If all the actions described	l above have <u>not</u> been undertaken, explain w	hy:
P. 10 15 20 0 D. (4) NM		
has begun, please attach a	a narrative of actions to date. If remedial e	mediation immediately after discovery of a release. If remediation fforts have been successfully completed or if the release occurred ease attach all information needed for closure evaluation.
regulations all operators are public health or the environmental to adequately investigated to adequately investigated.	required to report and/or file certain release notifinent. The acceptance of a C-141 report by the OC ate and remediate contamination that pose a threa	est of my knowledge and understand that pursuant to OCD rules and cations and perform corrective actions for releases which may endanger CD does not relieve the operator of liability should their operations have to groundwater, surface water, human health or the environment. In esponsibility for compliance with any other federal, state, or local laws
Printed Name: Mele	odie Sanjari	Title:Environmental Professional
Signature: Melod	<u>ie Sanjari</u>	Date: 3/2/2020
email: <u>msanjari@marat</u>	chonoil.com	Telephone: <u>575-988-8753</u>
OCD Only		
Received by: Ramon	a Marcus	Date: <u>3/3/2020</u>

Spill Calculation Tool



_	Length (ft.)	Width (ft.)	Avg. Liquid Depth (in.)	% Oil	Total Volume (bbls)	Water Volume (bbls)	Oil Volume (bbls)
Rectangle Area #1	125	50	0.5		46.38	46.38	0.00
Rectangle Area #2					0.00	0.00	0.00
Rectangle Area #3					0.00	0.00	0.00
Rectangle Area #4					0.00	0.00	0.00
Rectangle Area #5					0.00	0.00	0.00
Rectangle Area #6					0.00	0.00	0.00
Rectangle Area #7					0.00	0.00	0.00
Rectangle Area #8					0.00	0.00	0.00
-				Liquid Volume:	46.38	46.38	0.00
Saturated Soil Inputs:		Soil Type:	Gravel Loam Avg. Saturated		Total Volume	Water Volume	Oil Volume
Saturated Soil Inputs:		Soil Type:					
		Area (ft.)	Depth (in.)	% Oil	(bbls)	(bbls)	(bbls)
Rectangle Area #1		18750	0.5	0%	19.48	19.48	0.00
Rectangle Area #2		17000	0.125	0%	4.42	4.42	0.00
Rectangle Area #3		102500	0.1	0%	21.30	21.30	0.00
Rectangle Area #4				0%	0.00	0.00	0.00
							0.00
				0%	0.00	0.00	0.00
Rectangle Area #5 Rectangle Area #6				0% 0%	0.00	0.00	0.00
Rectangle Area #5							
Rectangle Area #5 Rectangle Area #6					0.00	0.00	0.00
Rectangle Area #5 Rectangle Area #6 Rectangle Area #7			5		0.00 0.00	0.00 0.00	0.00 0.00
Rectangle Area #5 Rectangle Area #6 Rectangle Area #7 Rectangle Area #8				0%	0.00 0.00 0.00 45.19	0.00 0.00 0.00 45.19	0.00 0.00 0.00 0.00
Rectangle Area #5 Rectangle Area #6 Rectangle Area #7 Rectangle Area #8	Recovered <i>and no</i>	t included in Stand	ling Liquid Inputs :	0% Saturated Volume	0.00 0.00 0.00 45.19	0.00 0.00 0.00 45.19 Water Volume	0.00 0.00 0.00 0.00
Rectangle Area #5 Rectangle Area #6 Rectangle Area #7 Rectangle Area #8	Recovered <i>and no</i>	t included in Stanc		0%	0.00 0.00 0.00 45.19	0.00 0.00 0.00 45.19	0.00 0.00 0.00 0.00
Rectangle Area #5 Rectangle Area #6 Rectangle Area #7 Rectangle Area #8	Recovered <i>and no</i>	t included in Stand		0% Saturated Volume	0.00 0.00 0.00 45.19	0.00 0.00 0.00 45.19 Water Volume	0.00 0.00 0.00 0.00
Rectangle Area #5 Rectangle Area #6 Rectangle Area #7 Rectangle Area #8	Recovered <i>and no</i>	t included in Stand		0% Saturated Volume	0.00 0.00 0.00 45.19	0.00 0.00 0.00 45.19 Water Volume	0.00 0.00 0.00 0.00 Oil Volume (bbls)
Rectangle Area #5 Rectangle Area #6 Rectangle Area #7 Rectangle Area #8	Recovered <i>and no</i>	t included in Stand		0% Saturated Volume	0.00 0.00 0.00 45.19 Total Volume (bbls)	0.00 0.00 0.00 45.19 Water Volume (bbls)	0.00 0.00 0.00 0.00 Oil Volume



INVOICE # 65832

NOVA TRUCKING, LLC 5800 NOVA DRIVE • HOBBS, NM 88240 OFFICE: (575) 393-8786

FAX: (5	75) 397-0042		
COMPANY	O! DA	TE Z	
LEASE 120 7300+ 700 743426	1/x y 5/4 RE	P/PO# 30-025	
START TIME // OO AM D PM D			
STOP TIME AM D PM D TOP GAUGE			
TOTAL HOURS BOTTOM GA	UGE		
OADING TANK #	BBLS LOADED SWD/LOCATION	35	
SWD COMPANY	TRANSFER		
SWD TICKET #			
RUCK NUMBER			
PRIVER (PRINT) SOY			
RIVER (SIGNATURE)			
MPANY REPRESENTATIVE (PRINT)			
PANY REPRESENTATIVE (SIGNATURE)			
IL BASE MUD FRESH WATER	PRODUCED WATER		ACID D
BASE MUD BRINE WATER	WASH OUT		LIQUID KCL D
rs_1/2/2 Off Sont	19/1000d.	7//////////////////////////////////////	
the work tank	But Tery		
E ON LOCATION	REASON		

REASON

E AT SWD