

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NRM2014856222
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party Marathon Oil Permian LLC	OGRID 372098
Contact Name Melodie Sanjari	Contact Telephone 575-988-8753
Contact email msanjari@marathonoil.com	Incident # (assigned by OCD)
Contact mailing address 4111 S. Tidwell Rd., Carlsbad, NM 8220	

Location of Release Source

Latitude 32.20598677

Longitude -104.05095012
(NAD 83 in decimal degrees to 5 decimal places)

Site Name: Fiddle Fee 23X 1H	Site Type: Oil & Gas
Date Release Discovered: 5/21/2020	API# (if applicable) 30-015-44094

Unit Letter	Section	Township	Range	County
H	23	24S	28E	Eddy

Surface Owner: ☐ State ☐ Federal ☐ Tribal ☒ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 140.04	Volume Recovered (bbls) 140
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

A corrosive mechanism resulted in a pinhole forming in the spool of the 1H separator on the location, which ultimately caused the release of approximately 140 bbl of fluid inside of the facility's containment and a small 15*5 area of overspray from the source between the containment wall, the electrical panel and the containment's stairs. A vac truck was dispatched to recover the standing fluids inside of the containment and repairs were to the separator were made. A 48 hour notice will be given to NMOCD before a liner integrity inspection is conducted.

Incident ID	NRM2014856222
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? >25 bbl released
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Yes, via email by Melodie Sanjari to NMOCD District II Reps on 5/22/2020	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why: 	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Melodie Sanjari</u>	Title: <u>Environmental Professional</u>
Signature: <u>Melodie Sanjari</u>	Date: <u>5/27/2020</u>
email: <u>msanjari@marathonoil.com</u>	Telephone: <u>575-988-8753</u>
<u>OCD Only</u> Received by: <u>Ramona Marcus</u> Date: <u>5/27/2020</u>	



Spill Calculation Tool

Standing Liquid Inputs:

	Length (ft.)	Width (ft.)	Avg. Liquid Depth (in.)	% Oil	Total Volume (bbls)	Water Volume (bbls)	Oil Volume (bbls)
Rectangle Area #1					0.00	0.00	0.00
Rectangle Area #2					0.00	0.00	0.00
Rectangle Area #3					0.00	0.00	0.00
Rectangle Area #4					0.00	0.00	0.00
Rectangle Area #5					0.00	0.00	0.00
Rectangle Area #6					0.00	0.00	0.00
Rectangle Area #7					0.00	0.00	0.00
Rectangle Area #8					0.00	0.00	0.00
Liquid Volume:					0.00	0.00	0.00

Saturated Soil Inputs:

Soil Type: Gravel Loam

	Length (ft.)	Width (ft.)	Avg. Saturated Depth (in.)	% Oil	Total Volume (bbls)	Water Volume (bbls)	Oil Volume (bbls)
Rectangle Area #1	15	5	0.25	0%	0.04	0.04	0.00
Rectangle Area #2				0%	0.00	0.00	0.00
Rectangle Area #3				0%	0.00	0.00	0.00
Rectangle Area #4				0%	0.00	0.00	0.00
Rectangle Area #5				0%	0.00	0.00	0.00
Rectangle Area #6				0%	0.00	0.00	0.00
Rectangle Area #7					0.00	0.00	0.00
Rectangle Area #8					0.00	0.00	0.00
Saturated Volume					0.04	0.04	0.00

Volume Recovered and not included in Standing Liquid Inputs:

% Oil	Total Volume (bbls)	Water Volume (bbls)	Oil Volume (bbls)

	Total Volume (bbls)	Water Volume (bbls)	Oil Volume (bbls)
Total Spill Volume (bbls):	0.04	0.04	0.00

Field Ticket
v **61102**Date 05-21-20

Co. Man _____

Truck # 333

AFE # _____

Customer Marathon o.i

Drilling Rig _____

Lease/Well # Fiddle Fee 23X1HTicket # 28394 = 1066-4553128395 = 1213-11048

Material Hauled (or work performed) Rerouted from previous load, Got called for spill at Fiddle Fee, Ran hoses and pickup 140 BBLs from containment area = separating tank, Took to NGL 2 loads Got in line to unload, Routed back to yard, after 2nd load, Post Trip Trip.
(pick up spill)

Lease or System Name

Well #

RRC #

From Fiddle Fee 23X1HTo NGLSWD

Time/Qty:	Description	Rate	Total
hrs.		@ _____ per hr.	= _____
<u>140</u> bbl/gal.	<u>Dirty Water Containment 1 1/4 Ld</u>	@ _____ per bbl/gal.	= <u>140</u>

Start Time: 230pm

Stop Time: _____

Total

Driver Name Pete Perez

Hours _____

I was not injured in an accident in the performance of this work. Employee Signature _____

Stamp & Sign

SERVICE ACKNOWLEDGED AND ARTICLES RECEIVED IN GOOD CONDITION UNLESS NOTED.
CUSTOMER SIGNATURE _____

White-Office

Yellow-Customer

Pink-Driver

TOTAL AMOUNT DUE WITHIN 30 DAYS OF THE INVOICE DATE.

Overdue invoices are subject to a late payment charge of 1.5% per month.
Customer shall be responsible for any and all reasonable attorney fees associated.