

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party: <i>Targa Resources</i>	OGRID
Contact Name: <i>Joseph Tillman Austin</i>	Contact Telephone: <i>575-631-7093</i>
Contact email: <i>jaustin@targaresources.com</i>	Incident # <i>(assigned by OCD)</i>
Contact mailing address: <i>PO Box 1689, Lovington, NM 88260</i>	

Location of Release Source

Latitude 33.31132 Longitude -103.61220
(NAD 83 in decimal degrees to 5 decimal places)

Site Name: <i>Bagley</i>	Site Type: <i>7" Steel Pipeline</i>
Date Release Discovered: <i>08/03/2020</i>	API# <i>(if applicable)</i>

Unit Letter	Section	Township	Range	County
<i>H</i>	<i>S4</i>	<i>T12S</i>	<i>R33E</i>	<i>Lea</i>

Surface Owner: ☒ State ☐ Federal ☐ Tribal ☐ Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

☐ Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
☐ Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	☐ Yes ☐ No
☐ Condensate	Volume Released (bbls)	Volume Recovered (bbls)
☒ Natural Gas	Volume Released (Mcf): <i>218.80</i>	Volume Recovered (Mcf): <i>0</i>
☐ Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release:

A leak was discovered on a Targa, 7-inch steel pipeline. This leak was the result of internal corrosion. Upon discovery of the leak Targa Resources isolated the leak until permanent repairs could be made. Targa determined that a section of pipe would be removed and replaced. During this event, Targa proceeded to isolate the section of pipe and replace the section of pipe with new pipe. After the line was verified to be safe to operate, Targa put the line back into service.

Form C-141

Page 2

State of New Mexico
Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? ☐ Yes ☒ No	If YES, for what reason(s) does the responsible party consider this a major release?
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

☒ The source of the release has been stopped. ☒ The impacted area has been secured to protect human health and the environment. ☐ Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. ☐ All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why: <i>This was a gas release only, there were no liquids released. The gas was emitted to atmosphere and no free-standing liquid accumulated on site.</i>	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Chris Price</u> Signature: <u></u> Email: <u>cprice@targaresources.com</u>	Title: <u>Area Manager</u> Date: <u>8-11-20</u> Telephone: <u>575-602-6005</u>
<u>OCD Only</u> Received by: _____ Date: _____	