Received by OCD: 8/19/2019 12:19:23 PM

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

)

Incident ID	nRM1925659370
District RP	
Facility ID	
Application ID	

# **Release Notification**

### **Responsible Party**

Responsible Party ConocoPhillips Company	OGRID 217817
Contact Name Gustavo Fejervary	Contact Telephone 432/210-7037
Contact email g.fejervary@cop.com	Incident # (assigned by OCD)
Contact mailing address 3300 N A ST. Midland Texas 79705	

### **Location of Release Source**

Latitude 32.79506

Longitude -103.47971

(NAD 83 in decimal degrees to 5 decimal places)

Site Name Vacuum Glorieta East Unit #20	Site Type flowline
Date Release Discovered 8/15/19	API# (if applicable) 30-025-37850 well flowline

Unit Letter	Section	Township	Range	County
G	32	17S	35E	Lea

Surface Owner: 🛛 State 🗌 Federal 🗌 Tribal 🗌 Private (Name: \_

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

Crude Oil	Volume Released (bbls) 2	Volume Recovered (bbls) 0	
Produced Water Volume Released (bbls) 45.5		Volume Recovered (bbls) 0	
	Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?	Ves No	
Condensate	Volume Released (bbls)	Volume Recovered (bbls)	
Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)	
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)	

Cause of Release Pipe corrosion.

#### State of New Mexico Oil Conservation Division

Incident ID	nRM1925659370
District RP	
Facility ID	
Application ID	

Was this a major release as defined by	If YES, for what reason(s) does the responsible party consider this a major release?			
19.15.29.7(A) NMAC?	Yes it was more than 25 bbls			
✓ Yes □ No ((16'x19'x1.5')+(38'x29'x1')+ (35'x7'x1'))x .15 (off pad effective porosity))/5.61= 47.5 bbls				
according to production rate only 2 bbls were oil and the rest was PW				
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?				
Yes, email sent to Bradford Billings, District 1 spill reporting email address and Dylan Rose-Coss				

### **Initial Response**

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

 $\checkmark$  The source of the release has been stopped.

 $\checkmark$  The impacted area has been secured to protect human health and the environment.

Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Gustavo Fejervary	Title: Environmental Coordinator
Signature: g.fejervary@cop.com	Date: <u>8/19/19</u> Telephone: <u>432/210-7037</u>
OCD Only Received by: Ramona Marcus	Date:9/13/2020

Form C-141 Page 3 State of New Mexico Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

# Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	(ft bgs)
Did this release impact groundwater or surface water?	🗌 Yes 🗌 No
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	🗌 Yes 🗌 No
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	🗌 Yes 🗌 No
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	🗌 Yes 🗌 No
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	🗌 Yes 🗌 No
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	🗌 Yes 🗌 No
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	🗌 Yes 🗌 No
Are the lateral extents of the release within 300 feet of a wetland?	🗌 Yes 🗌 No
Are the lateral extents of the release overlying a subsurface mine?	🗌 Yes 🗌 No
Are the lateral extents of the release overlying an unstable area such as karst geology?	🗌 Yes 🗌 No
Are the lateral extents of the release within a 100-year floodplain?	🗌 Yes 🗌 No
Did the release impact areas <b>not</b> on an exploration, development, production, or storage site?	🗌 Yes 🗌 No

Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.

#### Characterization Report Checklist: Each of the following items must be included in the report.

	Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells.
	Field data
	Data table of soil contaminant concentration data
	Depth to water determination
	Determination of water sources and significant watercourses within 1/2-mile of the lateral extents of the release
	Boring or excavation logs
$\square$	Photographs including date and GIS information

- Topographic/Aerial maps
- Laboratory data including chain of custody

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Form C-141	State of New Mexico	Incident ID
Page 4	Oil Conservation Division	District RP
		Facility ID
		Application ID
regulations all operators are public health or the environ failed to adequately investig addition, OCD acceptance of and/or regulations. Printed Name: Signature:	required to report and/or file certain release notine ment. The acceptance of a C-141 report by the C gate and remediate contamination that pose a thre	best of my knowledge and understand that pursuant to OCD rules and fications and perform corrective actions for releases which may endanger OCD does not relieve the operator of liability should their operations have eat to groundwater, surface water, human health or the environment. In responsibility for compliance with any other federal, state, or local laws 
OCD Only Received by:		Date:

Form C-141 Page 5 State of New Mexico Oil Conservation Division

Remediation Plan Checklist: Each of the following items must be included in the plan.

Detailed description of proposed remediation technique

Incident ID	
District RP	
Facility ID	
Application ID	

# **Remediation Plan**

<ul> <li>Scaled sitemap with GPS coordinates showing delineation points</li> <li>Estimated volume of material to be remediated</li> <li>Closure criteria is to Table 1 specifications subject to 19.15.29.12(C)(4) NMAC</li> <li>Proposed schedule for remediation (note if remediation plan timeline is more than 90 days OCD approval is required)</li> </ul>					
Deferral Requests Only: Each of the following items must be confirmed as part of any request for deferral of remediation.					
Contamination must be in areas immediately under or around production equipment where remediation could cause a major facility deconstruction.					
Extents of contamination must be fully delineated.					
Contamination does not cause an imminent risk to human health, the environment, or groundwater.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.  Printed Name: Title:					
Signature:	Date:				
email:	Telephone:				
OCD Only					
Received by:	Date:				
Approved Approved with Attached Conditions of	Approval Denied Deferral Approved				
Signature:	Date:				

State of New Mexico Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

# Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.				
A scaled site and sampling diagram as described in 19.15.29.11 NMAC				
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)				
Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)				
Description of remediation activities				
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.				
Printed Name:	Title:			
Signature:	Date:			
email:	Telephone:			
OCD Only				
Received by:	Date:			
Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.				
Closure Approved by:	Date:			
Printed Name:				